

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 3 Page(s) 1294)

- 
- Set post cor. of secs. 3, 4, 9 and 10, from which
- A Spruce 30" dia., bears N.30°W., 45 lks. dist.
  - A Spruce 36" dia., bears S.36°W., 107 lks. dist.
  - A Spruce 40" dia., bears N.39°E., (lks. omitted)
  - A Hemlock 24" dia., bears S.43°E., 22 lks. dist.

Survey by W.G. Corbitt; C. Boatman; J.K. Elliott - For: Crown Zellerbach - April 28, 1943 - C.S. File 52/91

-----

Found BTs at corner about 200 ft. West of old road, where a white and blue auto license plate is nailed on 5 ft. Spruce mkd. X.

Set 1½" Pipe and 2" x 2" x 4 ft. Fir post crayon mkd. S4 S3 S9 S10 T21S R12W., from which bears

- Orig. 24" Hemlock, really a 3 ft. Fir, S.43°E., 14.52 ft. to nail scribed 2, rest covered.
- Orig. 36" Spruce now 4 ft., S.36°W., 69.1 ft. to nail in overgrowth. A hole has been cut into this tree but the scribed face is not uncovered.
- Orig. 30" Spruce now 5 ft., N.30°E., 24.7 ft. to nail in overgrowth. The scribed face has never been uncovered.
- Orig. 40" Spruce now 4 ft., N.39°E., 44.7 ft. to nail in overgrowth. The scribed face has never been uncovered.

Cruiser's marks.

Ran North to lake and found 20" Alder with scars but it stands near cabins so may not be the orig. BT for MC. This line 13 ft. West of RR trestle about 150 ft.