

TOWNSHIP 21 RANGE 12 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4; 33 & 34 of T20-12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 7)

-----  
Set post corner of secs. 3, 4, 33 and 34, from which  
A Spruce 6" dia., bears N.4°E., 19 lks. dist.  
A Spruce 24" dia., bears N.43°W., 38 lks. dist.  
A Hemlock 18" dia., bears S.74°E., 44 lks. dist.  
A Fir 40" dia., bears S.30°W., 25 lks. dist.

Robert Ward, L.S. #1091 - For: Siuslaw National Forest & Tahkenitch Tree Farm Partnership - April 1995 - M 122-3 A

-----  
Found - 30" Rotted Spruce mound with a pitched slab scribed "BT" with chaining notch below (Rec. N.43°W., 25.1 ft)  
50" D.Fir, stump with what appears to be a X chopped across the healed blaze, I did not open (Rec. S.30°W., 16.5')

At intersection of record distances as determined from where the orig. face would have been, I set a 2½"x30" Aluminum corner monument w/cap stamped:  
T20S R12W

S33 S34  
S 4 S 3  
T21S  
1994  
LS 1091

BTs - 30" Rotted spruce mound, bears N.46¼°W., 27.7'  
50" D.Fir stump, bears S.27¼°W., 16.9'  
22" Hemlock stump, bears N.47½°E., 22.9'  
16" D.Fir stump, bears S.48¼°E., 8.7'

I drove a 5/8"x30" rebar with cap marked LS 1091 into the center of each stump.