

TOWNSHIP 21 RANGE 12 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 3 Page(s) 1281)

-----  
Set post cor. of secs. 10, 11, 14 and 15, from which  
A Fir 18" dia., bears N.72°E., 14 lks. dist.  
A Cedar 16" dia., bears S.63½°E., 14 lks. dist.  
A Cedar 24" dia., bears N.88°W., 20 lks. dist.  
A Cedar 30" dia., bears S.69°W., 21 lks. dist.

Douglas County Surveyors Office - R.B. Kimberling; P.L. Earle, crew - Feb. 8, 1978 - C.S. File 59/46-36

-----  
Found - A 6"x10"x13" sandstone rock with a chiseled 5" high "X" and "1916" (not of record) next to a squared wooden post.

An 18" now 38" Fir stump, uprooted with orig. stump hole, bearing approx. N.72°E., 9.2 ft. We open well healed scar and find a chopped out blaze.

A stump hole bears approx. S.63½°E., 9.2 ft.

A 24" now 22", barked, Cedar stump bears N.88°W., 13.2 ft. with a double, rotted out, blaze.

A 30" now 36" Cedar stump bears S.69°W., 13.9 ft. with scribing "R" in badly rotted double blaze.

Set a 1" x 36" I.P. with brass cap set at ground level, marked: "Douglas County Surveyor T21S R12W S10 S11 S15 S14 1978", from which

New BTs -6" D.Fir bears N.13°W., 11.6 ft. with scribing "T21S R12W S10 CS BT" in double blaze.

A 10" D.Fir bears N.50°E., 15.3 ft. double blazed and marked "S11 T21S R12W CS BT"

A 6" D.Fir bears S.12°E., 14.5 ft. double blazed and marked "T21S R12W S14 CS BT"

An 8" D.Fir bears S.32°W., 32.1 ft. double blazed and marked "T21S R12W S15 CS BT".

I do not disturb rock, the "X" bears NW. 0.7 ft.

From Schafer's Mill on Old Smith River Road, 1 mile North along railroad tracks to line crossing tag, then West 300 ft. ±.

FD Ok, 4/1/1996 by Clyde Mulkins, M 125-10