

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3; and 34, 35 T20-12

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 6)

Set post corner of secs. 2, 3, 34 & 35; from which
A spruce, 30" dia., bears N.74°E., 58 lks. dist.
Alder, 6" dia., bears S.75°E., 62 lks. dist.
Hemlock, 15" dia., bears S.38°W., 52 lks. dist.
Hemlock, 10" dia., bears N.58°W., 61 lks. dist.

Clyde Mulkins, surveyed for: Port Blakely Tree Farms; Scott Timber Co.; Menasha Corp. July 1997 - M 127-39

Found -
Replaced a rusted 2" iron pipe with a 5/8" x 36" rebar and a 2" alum. cap from which:
The remains of the orig. 30" Spruce (now a stump) with partial "reverse scribes" bears, N.74°E., 38.3 ft. set a 5/8" x 30" rebar with a plastic cap m k d . " L S 2006" in the center of stump remains.

New Accessories -
21" Hemlock, bears N.25°W., 42.1 ft. scribed "T20S R12W S34 BT"
30" Spruce, bears N.82°W., 64.3 ft. scribed "T20S R12W S34 BT"
25" Spruce, bears S.26°W., 31.0 ft. scribed "T21S R12W S3 BT"

Note - The corner falls in a swamp approx. 50 ft. east from the toe of a hill.

Found OK by T. Rambo, April 2002 - M140-7