

TOWNSHIP 21 RANGE 12 POINT IDENTIFIER # 700111

PRIMARY CORNER DESCRIPTION M.C. East bdy. Section 36

Alias 891270 Description M.C. Right bank Umpqua River
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 3 Page(s) 1149)

Right bank of Umpqua River
Set post, from which
 A Spruce 10" dia., bears N.15°E., 62 lks. dist.
 A Spruce 8" dia., bears N.31°W., 77 lks. dist.

Douglas County Surveyors Office - James W. Byron, Surveyor - John M. Powell, crew - C.S. File 54/1 - (no date on record, probably 1960's)

Corner searched for, not found.
Found unrecorded BTs for M.C. cor. of 36 31. Found some scribing on spruce stump and alder stump. This lies on Butter Creek Rd. near bridge to farm house.

BLM resurvey by Deborah M. Stephens and Harvey E. Wofford, under group #1521. Surveyed April 1990 thru April 1995. (DCSO records Vol. 51 Page(s) 19592)

Point for the meander cor. of secs. 31 and 36, on the right bank of the Umpqua River, at proportionate dist.; there is no remaining evidence of the original corner.

At the corner point

Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T21S
R12W R11W
S36 S31

MC
1991

from which

 A spruce, 60 ins. diam., bears N. 31° W., 69 lks. dist., mkd. T21S R12W S36 MC BT.

No other suitable accessories available.