

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 100600

PRIMARY CORNER DESCRIPTION Sec Cor for 6 & 7; 1 & 12 of T22-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 3 Page(s) 1335)

Set post, cor. of secs. 1, 6, 7, and 12, from which
A Fir 30" dia., bears N.70°E., 51 lks. dist.
A Fir 20" dia., bears N.68°W., 64 lks. dist.
A Fir 35" dia., bears S.68°W., 53 lks. dist.
A Fir 20" dia., bears S.18°E., 68 lks. dist.

B.H. McGillicuddy - For: Whipple Lumber Co. - April 1952
RM 1-40

Found - Old Post.
Orig. Fir, 20" S.18°E., 68 lks. dist., windfall, scribed.
All other bearing trees destroyed.
Placed new post 5" x 5" x 5 ft. and iron pin 1 1/8" x 16" long.
New BTs -14" Chinquapin S.30°E., 14.5 ft. mkd. T22S R4W S7 BT
42" Fir S.7°15'W., 40.1 ft. mkd. T22S R5W S1 BT.
38" Fir N.74°W., 57.9 ft. mkd. T22S R5W S1 BT.
18" Cedar N.15°30'E., 46.0 ft. mkd. T22S R4W S6 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, S.A. Bilow - April 22, 1959 - C.S. File 49/59-29

Found - Scribed stake and 1" Axle at corner.
Orig. 20" now 40", down and partly rotted, previously opened, shows good scribing, " ", S.18°E., 44.9 ft.
Orig. 20" now 40", down & partly rotted Fir N.68°W., 42.2 ft., shows old scars, no scribing left.
Orig. 35" now 44" shell of rotted Fir, S.68°W., 35.0 ft., shows old scars.
Orig. 30" now stump hole only, N.70°E., 33.7 ft.
Set Brass cap at cor. mkd: County Surveyors Office
T 22 S
R5W

S 1	S 6
S 12	S 7

 R4W
1959

Re. McGillicuddy survey, I use same BTs in NE and SE. I destroy scribing on BTs to NW and SW.
New BTs -20" Cedar bears N.16°E., 46.8 ft. scribed Tp22S R4W S6 BT. I add CS.
18" Chinquapin bears S.30°E., 14.8 ft. scribed Tp22S R4W S7 BT. I add CS.

(Cont. Next Page)

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 100600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 6 & 7; 1 & 12, T22-5

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

6" R.Fir bears N.64°W., 13.0 ft. scribed T22S R5W S1
CS BT.
6" Hemlock bears S.77°W., 30.8 ft. scribed T22S R5W
S12 CS BT.

Survey by Bruce A. Shaner - For: U.S. BLM - Aug. 30, 1972 -
M 42-68

Found - 1959 DCSO brass cap properly marked.
18" Chinquapin, scribes visible, bears S.30°E., 14.8
ft.
24" Cedar, scribes visible bears N.16°E., 46.8 ft.
12" D.Fir, bears N.62°W., 13.0 ft. (Rec. N.64°W)
40" orig. D.Fir, windfall, shows rotted face, bears
S.18°E., 44.9 ft.
Orig. 30" D.Fir, stump hole only, bears N.70°E.,
33.7 ft.
Found 4" x 4" Post scribed S1, S6, S7, S12, laying
by brass cap.
Scribed -An 18" Hemlock "T22S R5W S12 BT", bears S.26°W.,
112.6 ft.

BLM resurvey by James E. Jelley and Wayne L. Rogers, under
Group #1103, surveyed June/July 1982 (DCSO records Vol. 46
Page(s) 17592-93)

The Sec. Cor., perpetuated and recorded by McGillicuddy in
1952, by Byron in 1959 and Shaner in 1972, monumented with an
iron post, 1¼" dia., firmly set, projecting 10" above ground
with a 1959 DCSO brass cap, from which the remains of two
original bearing trees:

A root hole bears S.18°E., 68 lks. dist., with a down Fir
alongside, 34" dia., with fragmentary scribe marks
visible on an opened blaze.
A root hole bears N.68°W., 64 lks. dist., with a down Fir
alongside, 40" dia.; no marks visible.
and bearing trees mkd. by McGillicuddy
A Cedar 27" dia., bears N.16°E., 71 lks. dist., with
fragmentary scribe marks visible on an open blaze.
A Chinquapin 18" dia., bears S.27¼°E., 21½ lks. dist.,
with fragmentary scribe marks visible on an open blaze.
and a bearing tree by Byron
A Fir 19" dia., bears N.63 3/4°W., 20 lks. dist., with a
healed blaze.

(Cont. Next Page)

