

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 29

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 3 Page(s) 1346)

-----  
Set ¼ sec. post, from which  
A Fir 36" dia., bears N.31°E., 104 lks. dist.  
A Laurel 2" dia., bears S.1°W., 58 lks. dist.

O.F. Thiel - For: R. Booth - Feb. 1910 - Field Book 115 Page 27 (old Thiel book, 12)

-----  
Found old stake but both old trees gone.  
Marked: A Fir 16" S.83°E., 14 ft.  
A Fir 16" N.37°W., 20 ft.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #516 - Surveyed July 29/Aug. 23, 1963 - (DCSO records Vol. 32 Page(s) 13432)

-----  
The ¼ sec. cor. of secs. 20 and 29, determined at record bearing and distance from the remains of the original NE. bearing tree:

A rotted Fir stump 38" dia., bears N.37°E., 104 lks. dist. mkd. with a burned and pitched over face. No marks remain.

and a bearing tree of which I have no record:

A sawed Fir stump 32" dia., bears N.42°W., 16 lks. dist. mkd. 4 S on open blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

¼  $\frac{S\ 20}{S\ 29}$   
T 22 S R 4 W  
1963

from which new bearing trees:

A Fir 8" dia., bears N.49¼°W., 47 lks. dist. mkd. ¼ S20 BT  
A Fir 7" dia., bears S.78¼°W., 62 lks. dist. mkd. ¼ S29 BT

From this point, an iron pipe 1 3/4" dia., bears S.12½°E., 5½ lks. dist. protruding 8" above ground.

Fd. OK, Nov. 1993 - D. Baker - M 119-20

Fd. Ok, May 2005 by K. Hoffine - M 148-9A&B