

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 4 Page(s) 1362)

-----  
Set post 4" dia., 4 ft. long, with marked stone, 12" in ground for qr. sec. cor., marked ¼ S on N. face, from which  
A Laurel 12" dia., bears N.47°W., 55 lks. dist. mkd. ¼ S BT.  
A Fir 24" dia., bears S.32°W., 34 lks. dist. mkd. ¼ S BT.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under special instructions dated August 15, 1901 (DCSO records Vol. 4 Page(s) 1380)

-----  
¼ Sec. cor. is a Cedar post, 3" sq., 24" above ground marked as described by the surveyor general, from which  
A Fir 24" dia., bears S.32°W., 34 lks. dist. mkd. ¼ S BT. (Original BT)  
A Cedar 8" dia., bears N.10°W., 41 lks. dist. mkd. ¼ S3 BT. (New BT)

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - C. Putnam, crew - March 9, 1962 - C.S. File 49/42-54

-----  
Corner Report Only  
Found - 1" Iron pipe and squared stake.  
Cedar tree, now 17", scribed "¼ S3 HB". Scribing done about 24 years ago, about 1 ft. above ground.  
Old rotted face with axe cuts made about 55 to 60 years ago. No old scribing found. Tree bears N.10°W., 27 ft. from pipe.  
Fir stump 37" dia., bears S.32°W., 22.4 ft. Yellow tag, Woodard Lbr. Co. on stump. No scars or scribing found.  
No trace of Laurel BT found.  
No Vine Maple thicket in immediate vicinity as called for in Wright's 1884 notes.  
Did Not Renew.

Glen McChesney - For: Weyerhaeuser Co. - Aug. 26, 1963 - C.S. File 53/105-5

-----  
Found - No trace of original stone or post.  
12" Laurel N.47°W., 36.3 ft. Gone.  
24" Fir S.32°W., 22.4 ft., now 30" Fir stump, no visible scribing.  
(Cont. Next Page)

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO 1903, no mention of 1884 stone.  
8" Cedar N.10°W., 27.1 ft., scribing visible on 14"  
I.Cedar.  
Found 1" galv. I.P. used as hub by Woodard Lbr. Co.  
New BTs -52" I.Cedar stump N.7°E., 46.0 ft. added "W" nail  
and plate.  
16" Fir S.57°E., 19.0 ft. added "W" nail and plate.

BLM Resurvey, by Dale B. Bedell, Surveyed under Group No. 1703. Surveyed Aug. 1993 thru May 1994. (D.C.S.O. records Vol. 52 Page(s)19648 )

-----

The 1/4 sec. cor. of secs. 3 and 10, perpetuated by the Weyerhaeuser Lumber Company, in 1963 (Douglas County Surveyor's Office corner renewal record, T.22S., R.4W., No. 117), monumented with an iron pipe, 1 in. diam., firmly set, projecting 18 ins. above the ground, from which the remains of an original bearing tree:

- A fir stump, 40 ins. diam., bears S.32°W., 34 lks.dist., no marks visible.
- and a bearing tree mkd. by Thiel in 1903
  - A cedar, 24 ins. diam., bears N.10°W., 41 lks. dist., with scribe marks 1/4 S3 on an upper blaze and H on a lower blaze, and an older decayed blaze at the base of the tree.
- and bearing trees mkd. by the Weyerhaeuser Company
  - A cedar stump, 50 ins. diam., bears N.7°E., 70 lks. dist., with a nail, marked W on the head, driven into the base.
  - A fir, 18 ins. diam., bears S.57°E., 29 lks. dist., with a Weyerhaeuser metal tag.

At the corner point  
Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T22S      R4W  
1/4  $\frac{S}{S} \frac{3}{10}$   
1993

from which new bearing trees

- A fir, 7 ins. diam., bears S.87°E., 31 lks. dist., mkd. 1/4 S10 BT.
- A fir, 7 ins. diam., bears N.16°W., 10 lks. dist., mkd. 1/4 S3 BT.

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post and iron pipe alongside.