

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1356)

Set ¼ sec. post, from which
A Redwood 50" dia., bears S.50°E., 70 lks. dist.
A Fir 4" dia., bears N.66°W., 329 lks. dist.

Oscar Thiel - Wit: H.W. Kissling; Dan Wright - Nov. 1944 - C.S. File 61/5-5 (and "old" corner book, Vol. 1 Pg. 198)

Original bearing trees fallen. The SE tree, a large Cedar, (Redwood) being down a number of years, but there was sufficient evidence it was the original bearing tree. I was at the corner in 1911, the tree was standing.
Set sawed Fir post 4 x 4", 3 ft. long and drove an ironpipe 2" dia., 24" long, alongside.
Marked: A Fir 26" dia., which bears N.40°W., 14.7 ft. dist. and mkd. ¼ S.B.T. C.S.
A Fir 24" dia., which bears N.70°E., 34.5 ft. dist. and mkd. ¼ S.B.T. C.S.

Glen McChesney - For: Weyerhaeuser Co. - Jan. 28, 1958 - C.S. File 53/105-36

GL0 survey record, 1855:
Post, no trace original.
50" Redwood S.50°E., 70 lks.; not Redwood but Incense Cedar, uprooted, split and burned.
4" Fir N.66°W. 329 lks.; not found.
Found:
18" Fir snag 35 ft. high, scribed ¼ CS BT.
26" Fir, scribed.
2" rusted pipe and 4" square post scribed 1/4 S.
Accessories added this date: ("W" nails and plates)
26" Fir N.39°W., 13.8 ft. (CS BT)
10" Fir S.23°E., 7.7 ft.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & W. Stoffel, crew - Feb. 26, 1964 - C.S. File 49/59-43

Found - 1½" I.Pipe and 5" sq. Cedar stake, scribed, at corner.
36" Fir stump N.66°W., 217 ft., opened and found good scribing "1".
Stump hole, remains of old Cedar lying downhill from it, S.50°E., 46.2 ft., Cedar badly rotted and burned, no marks. (Cont. Next Page)

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

24" D.Fir snag, not orig. BT, N.69°E., 36.2 ft.,
scribing in wood, "¼S CS BT", no record of this
tree. (See above Thiel record)
Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 4 W
¼ S34 | S35
1964
Iron pipe badly rusted, set brass cap alongside cedar stake.
New BTs - 32" D.Fir N.42°W., 14.3 ft. mkd. ¼ S34 CS BT.
15" D.Fir S.20°E., 8.7 ft. mkd. ¼ S35 CS BT.
Corner lies on N. slope of hill, approx. 460 ft. North of
ridge.

Fd. OK, July 1988 by D. Peel - M 106-59
Fd. OK, June 1990 - M 110-39
FD. OK, May 1997 - by David Wellman - M 127-14

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 2/27/2009 - C.S. File 67/28-21 & C.S.
File 67/30 for map

Found - 2½" DCSO brass cap on 1½" O.D. iron pipe protruding
4" out of ground (1964) (BC properly marked)
2" dia., iron pipe protrudes 12" out of ground bears
0.5 ft. SW of BC/IP (1944)
15" now 32" dia., D.Fir with a fully healed blaze,
bears S.20°E., 8.7 ft. (agree with rec) 1964
32" now 36" dia., 4 ft. high D.Fir stump with a
fully healed blaze, bears N.42°W., 14.3 ft.
(agrees with rec) 1964.
24" rotted fir stump bears N.69°E., 36.2 ft. (agrees
with rec)
New - 13" dia., D.Fir double blazed & scribed "¼ S35 CS
BT" bears N.36°E., 23.5 ft.
4" dia., D.fir single blaze 3 ft above ground &
scribed "¼ BT" bears N.14°W., 19.8 ft.
Metal fence post set 1 ft. south of BC/IP.
Compass decl. 16½°E.