

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Survey by Frank O. Williams, LS #875 - For: Weyerhaeuser Co.
- May 16, 1983 - M 94-36

Set 1/2" x 24" I.Rod with plastic cap mkd: WEYER CO in mound
of stones., from which
37" Incense Cedar S.72°E., 29.9 ft.
27" Fir S.28½°W., 39.4 ft.
(Distance measurement to "W" nails)

Douglas Co. Surveyors Office - Randall Smith and Stephen
Flause, crew - Nov. 14, 1991 - C.S. File 64/21-11

Found - 1/2" Iron rod with plastic cap mkd. "Weyer Co.",
protrudes 12" above a 2 ft. x 4 ft. long mound of
stone.
3/4" I.D. x 35" long Iron pipe found loose in
ground, protruding 2 ft. above ground. I.P.
bears S.20°E., 1.0 ft. from iron rd. (source
unknown)
37" now 37" dia. I.Cedar with a fully healed single
blaze, bears S.75½°E., 29.9 ft. (Rec. S.72°E.,
29.9 ft.)
27" now 28" dia. D.Fir with a fully healed single
blaze bears S.24½°W., 39.4 ft. (Rec. S.28½°W.,
39.4 ft.)
(Distances taken to center at base. Record distances from
Weyerhaeuser taken to "W" nail.)
Position of 1/2" I.R. is referenced, (measures 28½" long).
SET a DCSO 2 3/8" dia. Brass cap on a 1 3/8" O.D. x 32" long
Iron pipe at referenced position. BC/IP protrudes 12" above
a 4 ft. long x 2 ft. wide x 1 ft. high mound of stone. 3/4"
I.D. Iron pipe is set along North edge of BC/IP., protruding
11" above ground. At corner, solid rock was hit approx. 6"
below ground surface. Cap is marked: Douglas County
Surveyors Office T22S C 1/4 S26 R4W 1991.
New BTs -13" dia. D.Fir double blazed and scribed "C ¼ S26 CS
BT" bears N.88½°E., 15.6 ft.
7" dia. D.Fir double blazed and scribed "C ¼ S26 CS
BT" bears N.57°W., 5.3 ft.