

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 4 Page(s) 1372)

Set post 4" dia., 4 ft. long, with marked stone, 12" in ground for qr. sec. cor., marked ¼ S on N. face, from which
A Fir 40" dia., bears S.80°E., 54 lks. dist. mkd. ¼ S BT
A Fir 5" dia., bears N.89°W., 43 lks. dist. mkd. ¼ S BT.

C.R. Jones - For: Woodard Lumber Co. - July 1958 - C.S. File 42/385 & C.S. File 53/1-45

Set 3/4" Iron pipe with scribed BTs as follows:
8" Fir N.73°E., 25.2 ft. scribed ¼ S BT.
8" Fir S.86°15'W., 17.0 ft. scribed P S BT.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Nov. 14, 1991 - C.S. File 64/21-10

Found - A 3/4" Iron pipe protruding 10" above ground.
Original BTs looked for, not found.
8" now 15" dia. D.Fir with a fully healed double blaze bears West, 17.0 ft. (Rec. S.86¼°W., 17.0 ft.)
8" now 20" dia. D.Fir with a fully healed single blaze bears N.81½°E., 26.2 ft. (Rec. N.73°E., 25.2 ft.)

3/4" I.D. Iron pipe is referenced and removed. (Measured 44" long)

Set a 1 3/8" O.D. x 32" long Iron pipe with a 2 3/8" dia. brass cap at referenced position of 3/4" I.P. Brass cap/I.P. protrudes 6" above ground. Cap is mkd:

Douglas County Surveyors Office

T 22 S R 4 W

¼ S 23
S 26

1991

3/4" I.P. is placed along West edge of BC/IP, protrudes 4" above ground.

New BTs -17" dia., D.Fir double blazed and scribed "¼ S23 CS BT" bears N.20°W., 20.8 ft.

12" dia. D.Fir double blazed and scribed "¼ S26 CS BT" bears S.0½°E., 51.5 ft.

Corner lies approx. 50 ft. East of a gravel road.

continued next page

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent resurvey by A. Bert Skeesick Cadastral Surveyor, and Robert H. Browning, Surveying Tech. Group No. 2170 surveyed Aug. 2007/Feb. 2008 - (DCSO records Vol. 55 Page(s) 21785-6)

The ¼ sec. cor. of secs. 23 and 26, reestablished by Jones, in 1958, subsequently perpetuated by the Douglas County Surveyor's Office in 1991. There is no remaining evidence of the original corner, therefore this position is accepted as the best available evidence of the original cor., monumented with an iron post, 1¼" dia., firmly set, projecting 6" above ground, with brass cap (properly) mkd.

from which the remains of bearing trees mkd. by Jones

A fir, 24" dia. bears N.83°E., 25.9 ft with a healed blaze

A sawed fir stump, 15" dia., bears S.87¼°W., 16.1 ft.
no marks visible.

and the remains of BTs mkd by the Douglas County Surveyor's Office

A sawed fir stump, 15" dia., bears S.0¾°W., 51.6 ft., with a healed blaze.

A fir, 19" dia. bears N.19½°E. 20.6 ft with a healed blaze and new bearing tree

A fir, 12" dia., bears S.71¼°W., 71.7 ft., mkd. ¼ S26 BT.