

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 3 Page(s) 1352)

Set ¼ sec. post, from which
A Fir 8" dia., bears S.79°E., 18 lks. dist.
A Fir 9" dia., bears N.30°E., 9 lks. dist.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under special instructions dated August 15, 1901 (DCSO records Vol. 4 Page(s) 1378)

I go to the ¼ sec. cor. bet. secs. 2 and 11, which having disappeared, I re-establish by setting a Fir post, 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., marked ¼ S2 on N. face and 11 on S. face, and witnessed as described by the surveyor general.

Douglas Co. Surveyors Office - Bruce Rogers, Deputy, Stone and Stoffel, crew - Jan. 1965 - C.S. File 53/101-71

Found - 9" Fir, orig. BT, now 40", N.30°E., 5.9 ft., chopped out, found scribing.
8" now 30" Fir, orig. BT, S.79°E., 11.9 ft., rescribed "¼ S11 CS BT".

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 4 W
¼ $\frac{S}{S}$ $\frac{2}{11}$
1965

New BT - 12" W. Fir N.25°W., 56.5 ft. mkd. ¼ S2 CS BT.