

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1414-15)</p> <p>-----</p> <p>Set ¼ sec. post, from which An Ash 6" dia., bears S.35°E., 57 lks. dist. Elias Stillwell's house bears S.65°E., 435 lks. dist.</p>
<p>O.F. Thiel - For: W.H. Lykes - March 1912 - Field Book 115 Page 52</p> <p>-----</p> <p>At the ¼ cor. bet. secs. 17 and 18, drove an iron pipe 1½" x 4 ft.</p>
<p>Wilford N. Haines - Oct. 1962 - M 24-23</p> <p>-----</p> <p>Found - 1½" Iron pipe as shown on survey by Irving, May 1946 (C.S. File 52/131) (Set by Thiel in 1912) Pipe has been covered by a rock fill. Orig. Ash BT, S.35°E., 57 lks., has been rescribed. Set Iron rod, ¾" dia. x 3 ft. long for ¼ S18 S17 T22S R5W.</p>
<p>Fd. OK, Feb. 1965, DCSO, B.Rogers, C.S. File 53/101</p>
<p>Douglas Co. Surveyors Office - John M. Powell, and crew - Nov. 12, 1970 - C.S. File 53/101-43</p> <p>-----</p> <p>Found - ¾" Iron rod at ¼ corner. Orig. Ash now 25", S.35°E., 32.6 ft., some scribe marks visible.</p> <p>Mkd. Bearing Objects: 2" Cross (+) on SW corner of concrete slab for diesel pump, South, 37.50 ft. 2" Cross (+) on SW corner of concrete slab for transformers, N.81°E., 63.30 ft.</p> <p>This corner falls in gravel area approx. 70.0 ft. North of road and South of log pond.</p>
<p>See also Haines survey in C.S. File 55/216 for sketch of corner and found accessories.</p>
<p>Fd. OK, July 1994, M 120-47 Fd. OK May 1998, by C. Sweeden - P. Plat 1998-0049 Fd. OK by C. Sweeden, Sept. 2001 - P. Plat 2001-0089 Fd. Ok by D. Edwards 5/2006 - M151-12 Fd. 5/8" IR by M Erickson 12/2015 - M170-38</p>