

PRIMARY CORNER DESCRIPTION Sec Cor for 32 & 33 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1388)

Set post cor. secs. 32 and 33, from which
A Fir 12" dia., bears N.23°E., 12 lks. dist.
A Dogwood 3" dia., bears N.78°W., 14 lks. dist.

Douglas Co. Surveyor - Bruce R. Rogers, Deputy - Wm. Stoffel and Mike Stone, crew - Feb. 1965 - C.S. File 53/101-28

Found - 12" Fir now 43", N.23°E., 8.0 ft., scribing visible "BT"

No trace of NW tree.

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S
S 32 | S 33 R5W
C C
1965

New BT - 8" Fir N.29°W., 45.5 ft. mkd. T22S R5W CC S32 BT.
Rescribe-43" Fir CC T22S R5W S33 CS BT.

Douglas Co. Surveyors Office - Clell Goodwin, Deputy - Gary Langlitz, Vic Cangie, Lenora Ladig, crew - Dec. 15, 1975 - C.S. File 57/39-1

Found - A 1" x 30" I.P. with brass cap properly stamped (1965 DCSO) projecting out of ground 8".

An orig. 12" now 42" Grand Fir opened to reveal orig. scribe marks and rescribed, bears N.23°E., 7.9 ft.

The stump hole from Rogers' 8" Fir scribed in 1965 bears N.29°W., 45.5 ft. (This tree is now blown down.)

There is no sign of the original Dogwood BT.

New BT - The most southerly of four trunks of a Maple with a common base, an 8" trunk scribed "CC T22S R5W S32 CS BT" in a double blaze, bears N.64°W., 36.9 ft.

The easiest route to this corner is through the property of Mr. Mays on Hayhurst Rd. and then NW up the creek bed. Corner lies about 300 ft. from the road and 40 ft. South of the creek.

BLM resurvey by James E. Jelley and Wayne L. Rogers, under Group #1119, surveyed 1982-84 (DCSO records Vol. 46 Page(s) 17680-81)

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 32 & 33 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

At the true point for the cor. of secs. 32 and 33 only,
Set an aluminum post, 28" long, 2½" dia., 24" in the ground,
with alum. cap mkd:

T 22 S R 5 W
S 32 | S 33
S 5
T 23 S R 5 W
1983

from which

A Grand Fir 10" dia., bears N.18½°E., 43½ lks. dist., mkd.
T22S R5W S33 BT.

A Fir 8" dia., bears N.33°W., 135 lks. dist., mkd. T22S
R5W S32 BT.

From this point, the original cor. of secs. 32 and 33 only,
bears S.0°02'W., 0.06 chs. dist., perpetuated and recorded by
Rogers in 1965, and further perpetuated and recorded by
Langlitz in 1975, monumented with an iron post, 1¼" dia.,
firmly set, projecting 8" above ground, with brass cap mkd.
COUNTY SURVEYORS OFFICE T22S R5W S32 S33 CC 1965, from which
the remaining original bearing tree

A Fir 50" dia., bears N.23°E., 12 lks. dist., with scribe
mark 3 visible on partially healed blaze.
and a bearing tree mkd. by Langlitz

A Maple 8" dia., bears N.65°W., 55 lks. dist., with scribe
marks 5W S32 CS B visible on partially healed double
blaze.

Survey by Ken Hoffine - For: Lone Rock Timber - Feb. 1994 -
M 118-66

Found - DCSO brass cap in good condition.
BLM brass cap bears N.0°15'E., 4.2 ft.
51" D.Fir bears N.23°E., 7.9 ft., healed scar, BLM
and County BT tags.
11" Maple bears N.64°W., 36.3 ft. (tag says 36.9
ft.) scribing visible. BLM tag.
11½" D.Fir bears N.33°W., 89.1 ft., well healed scar
and BLM tag.
17" Grand Fir bears N.18½°E., 38.5 ft. (Rec. 28.7
ft. is low stump) I tag tree.
Corner sits on NE side slope with logged brushy ground to
East.

continued next page

PRIMARY CORNER DESCRIPTION Sec Cor for 32 & 33 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike
- 12/14/2005 - C.S. File 67/13-18

Found - 3" dia., alum. cap (BLM) (properly mkd) on 2½" alum.
post, flush with ground.

2¼" dia. cap dated 1965 flush w/ground leans to west
This BC/IP bears South 4.2 ft from BLM AC/AP.

FROM 1983 BLM AC/AP

10" Grand Fir now 18" dia., x 4 ft. tall shattered
stump healed single blaze & tag visible, bears
N.18½°E., 37.4 ft. (rec. N.18½°E., 28.7 ft.) 1983
BLM tree.

8" Fir now 12" dia., x 4 ft tall rotting stump fully
healed blaze & tag visible, bears N.33°W., 89.1
ft. (agrees w/rec.) 1983 BLM tree

FROM 1965 DCSO BC/IP

8" maple now 11" dia., stump with multiple
re-sprouted stems above blaze height w/partial
scribing visible bears N.64°W., 36.9 ft. to DCSO
cap (agrees w/rec.) DCSO tree 1975

An orig. 12" Fir now 51" dia., x 6 ft. tall grand
fir stump, has been opened & only partially
healed back, bears N.23°E., 7.9 ft. to DCSO cap
(agrees w/rec) Orig. BT, 1855

New - FROM 1983 BLM AC/AP

24" dia., Grand Fir double blazed & scribed "CCCS
BT" bears S.26°E., 23.7 ft.

21" dia., Grand Fir double blazed & scribed "C Cor
CS BT" bears S.51½°W., 25.0 ft.

No suitable tree within range North of corner.

Note - Corner lies on moderate slope with timber to the
south.

Compass decl. 16¾°E.