

PRIMARY CORNER DESCRIPTION CE 1/16 Sec. 33

Alias	Description

BLM resurvey by James E. Jelley and Wayne L. Rogers, under Group #1119, surveyed Oct. 1982/Feb. 1984 (DCSO records Vol. 46 Page(s) 17688)

Point for the center E 1/16 sec. cor. of sec. 33.
Set an aluminum post, 28" long, 2½" dia., 24" in ground, with aluminum cap mkd.

$$C \frac{E \ 1/16}{1983} C$$

from which
A fir, 8" dia., bears N.9¾°E., 43 lks., mkd. X BT.
A fir, 11" dia. bears S.45½°E., 63 lks mkd. CE 1/16 S33 BT
The corner is located in ravine, drains N.35°E.

Douglas Co. Surveyors Office - Stephen J. Flauser - Mike Koch
- Aug. 5, 2013 - C.S. File 67/38-51

Found - The orig. 1983 BLM mon., a ¾" dia., alum. cap (properly mkd) on a 2½" O.D. alum. pipe, firmly and plumbly set protruding 3" above ground.
A fir, 8" dia., now a 13" dia., D.Fir with a fully healed high-low blaze; bears N.9¾°E., 29.5 ft. (rec. N.9¾°E., 28.4 ft.) Orig.
A fir, 11" dia., now an 11" dia., 7 ft. tall, rotted fir stump with evidence in bark of partially healed blaze, face is rotted away no scribing remains. This tree bears S.45½°E., 41.6 ft. (as per rec.) Orig.
New - A 6" dia., D.Fir scribed "X" "CSBT" on a high-low blaze; bears S.48¾°E., 22.3 ft.
Note - Monument is on moderate NE slope and on westerly edge of a shallow ravine. Monument is in older reprod fir forest with some maple, alder & willow.
Compass decl. 15½°E.