

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1403)</p> <p>-----</p> <p>Set post cor. of secs. 3, 4, 9 and 10, from which</p> <ul style="list-style-type: none"><li>A Fir 60" dia., bears N.25°E., 18 lks. dist.</li><li>A Fir 36" dia., bears N.38°W., 46 lks. dist.</li><li>A Fir 36" dia., bears S.72°W., 32 lks. dist.</li><li>A Fir 36" dia., bears S.10°E., 86 lks. dist.</li></ul>
<p>O.F. Thiel - For: Chas Schappers - June 1912 - Field Book 115 Page 64</p> <p>-----</p> <p>All old trees cut down to sec. cor.</p>
<p>Wilford N. Haines - May 1960 - M 11-68</p> <p>-----</p> <p>Found stumps of 2 bearing trees and a stake. Set 1" x 1" x 36" T-Iron.</p>
<p>Douglas Co. Surveyors Office - Bruce R. Rogers, deputy - Stoffel and Stone, crew - Jan. 1965 - C.S. File 53/101-40</p> <p>-----</p> <p>Found - T-Iron in E-W fence line set by Haines. (Corner is 45 ft. West of a road.)</p> <p>New BTs - 11" Fir N.22°W., 23.8 ft. mkd. T22S R5W S4 CS BT. 13" Fir N.66°E., 4.5 ft. mkd. T22S R5W S3 CS BT. 11" Madrone S.22°W., 25.5 ft. mkd. T22S R5W S9 CSBT 13" Fir S.53°E., 42.5 ft. mkd. T22S R5W S10 CS BT.</p>
<p>Fd. OK, Oct. 1983, R. Dean, M 95-64 A&amp;B Fd. OK, Sept. 1993, D.Baker, M 118-10 Fd. OK, Jan. 2001, Les Roberts, M 136-51</p>
<p>DCSO-GIS Corner visitation - 10/11/2005 - Typed: 1/18/2011 - C.S. File 67/33-1</p> <p>-----</p> <p>Monument - T-iron            Comment - 2 BTs standing</p>
<p>Fd. OK, June 2009, Carl Sweeden, V23 Pg 26A-B</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - April 14, 2011 - C.S. File 67/33-32</p> <p>-----</p> <p>Found - A 1"x1" Haines "T" iron (missing brass ID washer) is firmly set &amp; plumb monument protrudes 12" above ground. 1960</p> <p>continued next page</p>

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

OBT: A 60" dia., fir now a very rotted approx. 48" dia., 2 ft. tall fir stump with no remaining marks; bears N.32°E., 14.0 ft. (rec. N.25°E., 11.9 ft; this distance is good to orig. face)

OBT: A 36" dia., fir now a very rotted approx. 30" dia., 3 ft. tall fir stump with no remaining marks; bears N.38°W., 33.2 ft. (rec. N.38°W., 30.4 ft; this distance is good to orig. face)

1965: A 11" fir now a 20" dia., 1 ft. tall fir stump with a large spike nail set in top above center of the root crown; this tree shows no blaze or marks and bears N.22°W., 23.8 ft. (as per rec)

1965: A 13" fir now a 28" dia., 1 ft. tall fir stump with a large spike nail. Set in top above CRC; this tree shows no blazes or marks and bears N.66°E., 4.5 ft. (as per record)

1965: An 11" madrone now a 12" DBH madrone with a partially healed double blaze showing visible but illegible scribing; bears S.22°W., 25.5 ft. (as per record)

1965: A 13" D.Fir now a 28" DBH D.Fir with a fully healed single blaze; bears S.53°E., 42.5 ft. (as per record)

Monument is solid, we do not alter.

New - A 14" DBH Maple scribed "T22S R5W S4 CS" "BT" on a double blaze; bears N.60½°W., 42.9 ft.

A 13" DBH D.Fir scribed "T22S R5W S3 CS" "BT" on a double blaze; bears N.56½°E., 19.7 ft.

Note - Monument is on Northerly edge bench - Land at top of gentle NE slope in a very old reprod: Fir forest. Monument is just SW of forest access road and near a property line gate.

Compass decl. 15¾°E.

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Jeff Lorsung - 10/2/2018 (Filed 11/10/2021) - C.S. File 67/49-22

Found - A 1"x1"x36" Haines "T" iron broken in 2 pieces out of position.

New - We replaced the out of position monument using bearing and distances from the 1965 BTs by Rodgers in 1965 and the 2011 BTs by Flause. Set a 1" I.D. iron pipe 32" long, projecting 8" above the ground (Haines "T" deposited along the North edge) with a 2½" dia. brass cap marked as noted:

COUNTY SURVEYORS OFFICE  
T22S R5W  
S 4 | S 3  
S 9 | S10  
2018

continued next pg

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd BTs shown on Sketch -  
13" D.Fir in the NE quadrant  
Spike in stump in the NE quadrant  
28" D.Fir in the SE quadrant  
12" Madrone in the SW quadrant  
14" Maple in the SW quadrant  
No new bearing objects.

Note - The corner falls on a gentle Northerly slope in fir forest approximately 20 ft. Southwest of the access road.  
All bearing trees have BT Tags attached.  
Compass declination 14¾°E.