

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1398)

Set post cor. of secs. 10, 11, 14 and 15, from which
A Fir 4" dia., bears N.10°W., 5 lks. dist.
A Laurel 6" dia., bears N.75°E., 59 lks. dist.
A Laurel 4" dia., bears S.35°E., 5 lks. dist.
A Laurel 5" dia., bears S.35°W., 4 lks. dist.

Cor. Fd. and used in GL0 resurvey by W.P. Wright, under Contract #514 dated Aug. 1884 (DCSO rec. Vol. 4 Page 1422)

B.H. McGillicuddy - For: Whipple Lumber Co. - April 1952 - RM 1 - 40

Original BTs destroyed.
Post and 1" x 5 ft. Iron pipe.
Fir 30" N.10°W., 2.5 ft. mkd. T22S R5W S10 RP BT.
Fir 30" S.26°W., 41.9 ft. mkd. T22S R5W S15 RP BT.
Fir 32" S.31°E., 47.5 ft. mkd. T22S R5W S14 RP BT.
Fir 26" N.25°E., 25.0 ft. mkd. T22S R5W S11 RP BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; A. Bilow - Jan. 31, 1958 - C.S. File 49/59-3

Found - 3" x 3" sq. scribed post 2 or 3 years old and 3" x 3" sq. scribed stake 10 years old.
1½" Iron pipe 16" above ground. These monuments set record dist. and brg. from now 40" R.Fir which was partly open. I open to center, no old face or scribing found.
No trace of any original BTs found.
I believe this corner has not been renewed in proper place. I find scribing and faces on following trees scribed about 10 years or less.
30" R.Fir N.24½°E., 26.0 ft.
38" R.Fir S.29°E., 48.7 ft.
27" R.Fir S.29°W., 42.8 ft.

Bruce A. Shaner - For: U.S. BLM - Sept. 18, 1972 - M 49-12

Found - 1¼" Iron pipe 16" above ground and a 3" x 3" post, scribe visible.
36" D.Fir partly open, no scribe visible, bears N.10°W., 2.5 ft.
(Cont. Next Page)

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

30" D.Fir scribing visible, bears N.25°E., 26.0 ft.
(Rec. 25.0 ft.)
28" D.Fir face visible, bears S.29°W., 42.8ft. (Rec.
S.26°W., 41.9 ft.)
36" D.Fir stump, partially uprooted, face visible,
bears S.23½°E., 50.7 ft. (Rec. S.31°E., 47.5 ft.)
Set Brass cap mkd: T22S R5W WM S10 S11 S15 S14 1972. Placed
iron pipe beside brass cap.

Survey by Donald Peel, LS #752 - For: Weyerhaeuser Company -
Jan. 1988 - M 105-54

CORNER REPORT ONLY
Found - 1¼" Iron pipe with brass cap.
33" Fir N.72½°E., 60.8 ft., closed face. No record
36" Fir stump S.27¼°E., 50.8 ft.
32" Fir S.27½°W., 42.7 ft., closed face.
38" Fir stump N.7°W., 3.8 ft.
30" Fir N.26°E., 25.5 ft., closed face.