

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 3

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 4 Page(s) 1425)

Set post 4" dia., 4 ft. long with marked stone 12" in ground for 1/4 sec. cor. mkd. 1/4 S on W. face; from which
An Oak 20" dia., bears S.49°W., 203 lks. dist. mkd. 1/4 S BT
A Fir 14" dia., bears S.5 3/4°E., 360 lks. dist. mkd. 1/4 S BT.

O.F. Thiel - For: N.A. Koepka - Aug. 17, 1926 - Field book 116 page 4

Intersect E. of 1/4 cor. set by a former survey. Moved post South 45 lks. (Cedar Post). Marked:
Fir 8", S.41°W., 26 lks.
Fir 12", N.48°W., 15 lks.

Corner searched for, not found. DCSO, B. Rogers - April 1, 1965 - C.S. File 53/101-37

Troy Rambo - For: Bear Creek Timber Co. -1/2004 - M143-75

Set - 5/8"x30" rebar with a 2" alum. cap mkd: LS 2865
Scribed "1/4 S2 BT" on a 13" DF - bears S.77°E., 12.3 ft.
Scribed "1/4 S2 BT" on a 12" DF - bears S.7°E., 19.4 ft.
Set - 5 1/2" steel post 1' north
Note- Corner falls on a north - south cutting line
No other trees available.
All new BTs were measured to a 6" spike at side center base. Bearings were measured with a hand compass with a decl. of 17°E.

DCSO-GIS Corner visitation - 10/11/2005 - Typed: 1/18/2011 - C.S. File 67/33-1

Monument - rebar w/alum cap.
Comment - OK both BTs of rec. standing.