

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 540700

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 2; and S. 35, T21-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 791)

Set ¼ sec. post, from which
A Laurel 6" dia., bears N.50°E., 111 lks. dist.
A Laurel 6" dia., bears S.63°E., 41 lks. dist.

Survey by B.H. McGillicuddy - Wit: Marvin; Yoder; Martin; Olson - July 1953 - C.S. File 41/182

Placed 1½" x 42" Axle.
Marked new BTs:
36" Fir S.85°W., 70.7 ft. mkd. ¼ S BT.
24" Fir stump N.60°W., 195 ft. mkd. ¼ S BT.
No original BTs existing.

FD. OK, Dec. 1997 by Les Roberts - M 128-1

Troy Rambo - For: Bear Creek Timber Co. - 1/2004 - M143-75

Found - 1½" axle.
19" DF (Shaner 1994) bears S.64°W. 7.0 ft.
New - Scribed "¼ S2 BT" on 19" DF, bears S.42°E., 13.5 ft.
Scribed "¼ S2 BT" on 20" DF, bears S.87°E., 30.3 ft.
Set - 5½' steel post 1' north.
Note - Corner falls on a fresh East - West cutting line.
All new BTs were measured to a 6" spike at side center base. Bearings were measured with a hand compass with a decl. of 17°E.

DCSO-GIS Corner visitation - 10/13/2005 - Typed: 1/18/2011 - C.S. File 67/33-1

Monument - axle. Comment - OK, 3 live BTs

Fd. Ok by C. Sweeden, 6/2009 - 2009-0036
Fd. Ok by C. Sweeden, 6/2010 - 2010-0038