

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 4 Page(s) 1419)

-----  
Set post 4" dia., 4 ft. long with marked stone 12" in ground for ¼ sec. cor. mkd. ¼ S on W. face; from which  
A Fir 8" dia., bears N.40°E., 104 lks. dist. mkd. ¼ S BT.  
A Fir 8" dia., bears N.41°W., 200 lks. dist. mkd. ¼ S BT.

Survey by B.H. McGillicuddy - For: Whipple Lumber Co. - April 1952 - RM 1-40

-----  
Post. Found one bearing tree  
Fir 8" N.41°W., 200 lks., now 40" Fir. No scribe visible.  
(8" Fir N.40°E., 104 lks. destroyed)

Bruce A. Shaner - For: U.S. BLM - Sept. 18, 1972 - M 49-12

-----  
Found - Orig. 40" D.Fir, face visible, bears N.41°W., 132.0 ft.  
Set Brass cap mkd. T22S R5W WM S11 S12 ¼S 1972.  
New BTs -8" D.Fir bears N.19°E., 12.9 ft. scribed ¼S S12 BT.  
10" Madrone bears N.77°W., 20.5 ft. scribed ¼S S11 BT.  
N-S fence line runs 1 ft. East of the brass cap. E-W fence line, now partially destroyed, approx. 30 ft. North of the corner. This cor. is the same as recorded by McGillicuddy in his 1952 survey as per both BTs and fence lines.