

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 4 Page(s) 1419)

Set Post 4" dia. 4 ft. long with mkd. stone, 12" in ground for cor. to secs. 1, 2, 11 and 12, mkd. T22S S1 on NE.; R5W S12 on SE.; S11 on SW.; S2 on NW. face with 1 notch in E. and 5 notches in S. edges; from which
A Fir 40" dia., bears N.19°W., 45 lks. mkd. T22S R5W S2 BT
A Fir 10" dia., bears S.43°E., 43 lks mkd. T22S R5W S12 BT
A Cedar 5" dia., bears S.30°W., 17 lks mkd T22S R5W S11 BT
A Maple 4" dia., bears N.12°E., 25 lks mkd. T22S R5W S1 BT

Survey by B.H. McGillicuddy - For: Whipple Lumber Co. - April 1952 - RM 1-40

Original bearing trees destroyed.
Corner established by orig. blaze intersection & found rock.
New post in pile of rocks from which scribed BTs:
24" Cedar S.37°E., 28.1 ft. mkd. T22S R5W S12 R P BT.
13" Fir S.85°W., 24.9 ft. mkd. T22S R5W S11 R P BT.
54" Fir N.46°W., 49.1 ft. mkd. T22S R5W S2 R P BT.
30" Fir N.16°E., 19.4 ft. mkd. T22S R5W S1 R P BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; S Bilow - Jan. 29, 1958 - C.S. File 49/59-9

Found - Orig. 10" now 30" W.Fir S.43°E., 28.4 ft. I open and find good scribing "/ \".
Orig. 40" now 50" Fir snag, N.19°W., 29.7 ft. This BT has been burned, bark damaged, no scribing found. Checks record bearing and distance.
I find 3" x 3" scribed square stake and mound of stones which bears N.44°E., 68.4 ft. from brass cap I set for sec. corner. Also find BTs scribed for sq. stake corner. I believe this cor. established less than 5 years ago. I can find no trace of any orig. BTs at sq. stake corner.

Set Brass cap at cor. mkd:

County Surveyors Office
T 22 S R 5 W
S 2 | S 1
S 11 | S 12
1958

New BTs -17" W.Fir bears S.87°W., 24.8 ft. scribed S11 T22S R5W CS BT.
12" Hemlock bears N.32°W., 1.5 ft. scribed S2 T22S R5W CS BT.

continued next page

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 and 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

24" R.Fir bears N.72°E., 36.0 ft. scribed S1 T22S R5W CS BT. Rescribed orig., now 30" W.Fir, S.43°E., 28.4 ft. S12 T22S R5W CS BT.
Douglas Co. Surveyors Office - James Byron - April 22, 1959 -C.S. File 49/59 ----- On this date I destroy all scribing on BTs and I remove cor. stake as set NE of brass cap.
Fd. OK, May 20, 1965, DCS0, B.Rogers, C.S. File 53/101-14
Corner Fd. by B.A. Shaner, Aug. 1972, M 42-68 (Shaner also found McGillicuddy corner, 68.4 ft. N.44°E.)
County Cor. Fd. and used in BLM resurvey by Jelley and Rogers, under Contract #1103, surveyed June/July 1982. (DCS0 records, Vol. 46 Page 17594)
DCS0-GIS Corner visitation - 10/12/2005 - Typed: 1/19/2011 - C.S. File 67/33-1 ----- Monument - 1¼" IP w/BC Comment - ok, 3 standing BTs
Fd. Ok by Kris DeGroot, 7/2007 - M153-59
Kristian DeGroot - For: Silver Butte Timber Co. - Jan. 2014 - M167-14 ----- Found - A 1¼" iron post by Byron in 1958, firmly set in the base of the NW Hemlock BT, projecting 10" above the ground, with a 2½" brass cap (properly) mkd. All bearing trees of record are standing and in good condition. The original SE bearing tree: A 33" Hemlock (S.43°E., 43 lks), is now a high stump from recent logging in sec 12. NAD83 CORS96 (EPOCH 2002.00) Geodetic Coordinates Latitude: 43°40'41.59232"N Longitude: 123°14'52.65083"W