

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION Sec Cor for 13 & 24; 18 & 19, T22-4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCS0 records Vol. 3 Page(s) 1334)

-----  
Set post, cor. of secs. 13, 18, 19 and 24, from which  
A Maple 10" dia., bears S.83°E., 25 lks. dist.  
A Fir 40" dia., bears S.52°W., 61 lks. dist.  
A Fir 8" dia., bears N.112°W., (??) 86 lks. dist.  
A Fir 8" dia., bears N.37°E., 53 lks. dist.

Oscar F. Thiel - For: Watkins and Seals - June 2, 1903 - C.S. File 64/48 Page 10

-----  
Set a White Fir post. SE BT gone.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; S.A. Bilow - Jan. 8, 1958 - C.S. File 49/59-10

-----  
Found - Rotted Fir stump, 12" dia., N.42°W., 56.8 ft., showing "BT" scribe when cut open.  
Remnants of rotted Fir stump, N.37°E., 35.0 ft., Too far gone to find scribing.  
Fir stump, now 54" dia., S.52°W., 40.3 ft., (dist. from face of 40" tree) This tree had apparently been bark scribed. No bark left on side of stump facing corner.  
No trace of SE BT could be found.  
Corner lands in fence corner, fences running N.; S.; and W.

Set Brass cap at cor. mkd: County Surveyors Office  
T 22 S  
R S13 | S18 R  
5 S24 | S19 4  
W 1958 W

Blaze and scribe the following BTs:  
11" W.Fir S.36°E., 25.8 ft. "T22S R4W S19 CS BT"  
9" D.Fir N.74°E., 27.8 ft. "T22S R4W S18 CS BT"  
7" W.Fir S.36°W., 18.9 ft. "T22S R5W S24 CS BT"  
12" D.Fir N.71°W., 80.8 ft. "T22S R5W S13 CS BT", one blaze.

Fd. OK, Dec. 1987, D.Peel, M 105-27 Fd. OK, July 1992, R.Dolan, M 115-37  
Fd. OK Aug. 1999 by D. Baker - M132-16