

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1452)

-----  
Set ¼ sec. post, from which  
A Fir 10" dia., bears N.5°W., 48 lks. dist.  
A Redwood 36" dia., bears S.27°W., 28 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy & C. Putnam, crew - Sept/Oct 1961 - C.S. File 49/143-82

-----  
Found - 3/4" Bolt with 1¼" sq. head. (Probably from Plat of Sunnydale Orchards, Vol. 5 Page 20 A&B, 1914 - per V.L., 1995)  
Fir snag, now 34", N.5°W., 31.7 ft. to face. Shows 2 good scars. Did not cut open.  
Cedar tree, now 48", S.17°W., (instead of S.27°W.) 18.5 ft. to face. This tree has been opened previously and good scribing "¼S" visible.

Alongside Bolt, Set Brass cap at cor. mkd:  
County Surveyors Office  
T 22 S R 6 W  
¼  $\frac{S}{S}$   
1961

New BTs -7" D.Fir N.74°E., 19.3 ft. mkd. ¼ S5 CS BT.  
6" D.Fir S.40°E., 22.1 ft. mkd. ¼ S8 CS BT.

Fd. OK, Oct. 1995 by Edwards - M122-72; CS 63/100-5

Ronald L. Rice, Ward NW - For: Seneca Jones Timber Co. - 12/2007 - M 154-72

-----  
Found - Douglas Co. Brass cap dated 1961 with the following accessories:  
11" D.Fir bears S.40°E., 22.1' healed face  
14" X 12' burned D.Fir snag bears N.5°W., 31.7' - Burned face  
48" rotten incense cedar stump bears S.17°W., 18.5' To face - rotted face  
New BT - 7" D.Fir bears N.52°W., 35.2', blazed scribed "¼ S5 BT"

Fd. 1961 BC by D.Edwards - 8/2017 - M173-52