

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664 dated May 23, 1896 (DCSO records Vol. 4 Page(s) 1481)

Set a sandstone, 16x12x8 ins., 11" in the ground, for ¼ sec. cor. mkd. ¼ on W. face; from which
A Fir 12" dia., bears N.13½°W., 27 lks. dist. mkd. ¼ S BT.
A Fir 20" dia., bears S.45°E., 52 lks. dist. mkd. ¼ S BT.

Wilford N. Haines - Field Book H-108 (date?)

Orig. stone, 16x12x8.
12" Fir N.13½°W., 17.82 ft.
20" Fir S.45°E., 34.32 ft.
New trees:
18" Fir N.14°20'W., 18.20 ft.
36" Fir S.43°45'E., 36.30 ft.

Wilford N. Haines - For: E.G. Whipple Mill - Jan. 15, 1959 - M 13-66

Found old BTs.
Set Lot marker, 1" x 1" x 36" T Iron with cap inscribed "Survey Point, Wilford N. Haines #239"

Fd. OK, April 1997 by Ken Hoffine, C.S. File 65/13-8

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor Under Group No. 2653, Surveyed June/July 2012 - DCSO records Vol. 58 Page(s) 22987

The ¼ sec. cor. of secs. 32 and 33, perpetuated by Haines, in 1958, monumented with a "T" shaped iron rod, 3/4" dia., firmly set, projecting 11" above ground, with brass disk attached, mkd. WILFORD N HAINES 239 SURVEY POINT DRAIN ORE, from which the remains of the original bearing trees

A fir, 42" dia., bears S.45°E., 34.3 ft., with a healed blaze.

A fir snag, 23" dia., bears N.13½°W., 17.8 ft., with a healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 26" in the ground, directly over the "T" shaped iron rod, with brass cap mkd.

¼
S 32|S 33
2012

continued next page

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

from which

A fir, 20" dia., bears S.32°W., 11.2 ft., mkd. ¼ S32 BT.
Bury a magnet in a white plastic case at the base of the
stainless steel post.

Corner is located on an E. slope, 180 ft. N. of a ravine,
drains N.80°E.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral
Surveyor, under Group No. 2875, surveyed Aug. 2017/Feb. 2019-
(DCSO records Vol. 59 Page 23645-6)

The ¼ sec. cor. of secs. 32 and 33, monumented with an iron
post, 2½" dia., firmly set, projecting 1" above ground, with
a brass cap (properly) mkd.

from which the remains of the original bearing trees

A fir, 42" dia., bears S.45°E., 34.3 ft., with a healed
double blaze.

A decayed fir snag, 23" dia., bears N.13½°W., 17.8 ft.,
with a healed blaze.

and a bearing tree mkd. by Skeesick in 2012

A fir, 21" dia., bears S.32°W., 11.2 ft., with no marks
visible on partially healed blaze.