

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1450)

Set ¼ sec. post, from which
A Yew 48" dia., bears S.85°W., 86 lks. dist.
A Yew 12" dia., bears N.74°E., 124 lks. dist.

Survey by George Scroggin - For: Plat of Sunnydale Orchards -Aug. 6, 1914 - Plat Vol. 5 Page 20 A&B

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - Sept. 1961 - C.S. File 49/143-84

Found - 1" Bolt with 2¼" square head.
Fir tree, now 66", S.85°W., 56.8 ft. No scars or scribing visible.
Badly burned Fir stump N.74°E., 81.8 ft. Too much burned away to find any markings.
Bolt at corner, Brass cap set alongside bolt mkd: County Surveyors Office 1961 T22S R6W ¼ S5|S4.
New BTs -18" I.Cedar S.56°E., 4.5 ft. mkd. ¼ S4 CS BT.
24" D.Fir S.24°W., 8.5 ft. mkd. ¼ S5 CS BT.

Kent Inman - Seneca Jones Timber Co. - May 2010 - M160-72A&B

Found - 2½" BC on a 1" iron pipe, up 12" (properly) mkd. A metal T post was placed 1' south of the monument.
36" D.Fir, with a healed face and Haines and BLM BT tags. bears S.24°W., 8.5'
27" cedar, with a healed face and BLM BT tag, bears S.56°E., 4.5'
New - 7" D.Fir, bears N.40°W., 29.9' scribed ¼ S5 BT.
9" D.Fir, bears N.12°E., 36.5' scribed ¼ S4 BT.