

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1450)

Set ¼ sec. post, from which
A Fir 8" dia., bears N.14°E., 138 lks. dist.
A Fir 15" dia., bears S.20°E., 53 lks. dist.

Survey by George Scroggin - For: Plat of Sunnydale Orchards, Aug. 6, 1914 - Plat Vol. 5 Page 20 A&B

Bolt.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy & C. Putnam, crew - Sept/Oct 1961 - C.S. File 49/143-89

Found - 3/4" Bolt at corner with 1" sq. head.
Rotten stump of Fir, N.14°E. 191.1 ft. Good scribing "BT".
Badly burned Fir stump S.20°E., 35.0 ft., shows evidence of having been opened previously, no scribing found.

Alongside Bolt, Set Brass cap at cor. mkd:
County Surveyors Office

T 22 S R 6 W

¼ $\frac{S}{S}$ $\frac{4}{9}$

1961

New BTs -10" D.Fir N.12°W., 137.0 ft. mkd. ¼ S4 CS BT.
9" W.Fir S.14°E., 113.3 ft. mkd. ¼ S9 CS BT.

Kent Inman - Seneca Jones Timber Co. - May 2010 - M160-72A&B

Found - 2½" brass cap on a 1" iron pipe, up 10" (properly) mkd. A metal U post was placed 1" west of the monument.

31" D.Fir with a healed face, bears N.12°W., 137.0'.
I attached a new tag.

New - 7" D.Fir, bears S.53°E., 23.2' scribed ¼ S9 BT.
19" D.Fir, bears S.31°W., 78.8' scribed ¼ S9 BT.
6" D.Fir, bears N.83°E., 71.2' scribed ¼ S4 BT.