

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. Sec. 4 only, T23-6

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1428)

-----  
Set standard 1/4 sec. post, from which  
A Cedar 15" dia., bears S.70°E., 41 lks. dist.  
A Yew 20" dia., bears S.15°W., 23 lks. dist.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Special Instructions dated Oct. 27, 1897 (DCSO records Vol 4 Pg 1473)

-----  
I make diligent search, but cannot find old standard 1/4 sec. cor.  
Set sandstone 16x12x6 ins., 10" in the ground for standard 1/4 sec. cor., mkd. S C 1/4 on S. face; from which  
A Cedar 12" dia., bears S.44°E., 19 lks. mkd. S C 1/4 S BT.  
A Fir 20" dia., bears S.50°W., 39 lks. mkd. S C 1/4 S BT.  
This cor. is on the SE. slope of ridge, 75 ft. above last spur.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12629)

-----  
The standard 1/4 sec. cor. of sec. 4, monumented with a sandstone, 16x12x6 ins., firmly set, mkd. SC 1/4 on S. face, from which the remains of the original bearing trees:  
A Cedar stump, burned, 12" dia., bears S.44°E., 19 lks.  
A Fir 48" dia., bears S.50°W., 39 lks. dist., with a healed blaze.

At the corner point  
Set an iron post, 3 ft. long, 1" dia., 24" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:

1/4 S 4  
S C  
1955

Fd. OK - Ken Hoffine - Dec. 1995 - C.S. 65/2-1

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor Under Group No. 2653, Surveyed June/July 2012 - DCSO records Vol. 58 Page(s) 22982

-----  
The standard 1/4 sec. cor. of sec. 4 only, on the N. bdy. of T. 23 S., R. 6 W., monumented with an iron post, 1 1/4" dia., firmly set, projecting 10" above ground, in a collar of stone, with brass cap (properly) mkd.

continued next page

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 349100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. Sec. 4 only, T23-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of a bearing tree mkd. by Nicklin  
A sawed fir stump, 61" dia., bears S.50°W., 25.7 ft., with  
a healed blaze.

and new accessories

An iron rod, 30" long, 5/8" dia., driven 28" in the ground  
for a reference monument, bears S.30°58'11"E., 14.29  
ft., with aluminum cap mkd. RM T23S R6W S4 14.3 FT TO  
COR 2012 and an arrow pointing to the cor.

An iron rod, 30" long, 5/8" dia., driven 23" in the ground  
for a reference monument, bears S.56°20'30"W., 18.65  
ft., with aluminum cap mkd. RM T23S R6W S4 18.6 FT TO  
COR 2012 and an arrow pointing to the cor.

Corner is located on a steep E. slope, 130 ft. W. of a  
ravine, drains N.10°W., and 60 ft. N. of a ravine, drains  
N.64°E.