

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Pg 1454)

Set 1/4 sec. post, from which
A Fir 8" dia., bears N.32°W., 11 lks. dist.
A Fir 5" dia., bears S.48°W., 13 lks. dist.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #517, surveyed Aug/Sept. 1963 (DCSO recs Vol 32 Page 13448)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
1/4 S 22
S 27
T 22 S R 6 W
1963

from which
A Fir 13" dia., bears N.65°W., 104 lks. mkd. 1/4 S22 BT.
A Fir 10" dia., bears S.42°W., 47 1/2 lks. mkd. 1/4 S27 BT.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2500, Surveyed July/Aug. 2010 - (DCSO records Vol. 57 Page(s) 22809 & Survey plat 2012-1)

The 1/4 sec. cor. of secs. 22 and 27, monumented with an iron post, 2 1/2" dia., firmly set, projecting 2" above ground, with a brass cap (properly) mkd.
from which the remains of bearing trees mkd. by Beck
A roothole bears S.42°W., 31.4 ft., uphill of which is an uprooted, decayed fir, 16" dia., with a healed blaze.
A sawed, decayed fir stump, 28" dia., bears N.65°W., 68.6 ft., with a healed blaze.
and new bearing trees
A fir, 10" dia., bears N.73 1/2°E., 8.8 ft., mkd. 1/4 S22 BT.
A fir, 18" dia., bears S.44°E., 27.6 ft., mkd. 1/4 S27 BT.