

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22, 23, 26 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1440)

Set post cor. of secs. 22, 23, 26 and 27, from which
A Fir 12" dia., bears N.22°W., 15 lks. dist.
A Fir 12" dia., bears N.48°E., 49 lks. dist.
A Fir 10" dia., bears S.40°W., 2 lks. dist.
A Redwood 12" dia., bears S.58°E., 54 lks. dist.

Wilford N. Haines - Dec. 1958 - M 14-23 and Field book H-109

Found all BTs down.
Set Lot marker, a 1" x 1" x 36" T Iron with brass cap inscribed Survey Point-Wilford N. Haines #239.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy, C. Putnam, crew - Aug. 1961 - C.S. File 49/143-42

Found - Haines T Iron and cap.
Fir stump, now 20", N.22°W., 9.9 ft., uprooted and down. This tree previously opened and scribing "22" and "6W" visible in opened face. Later bark scribing also on stump.
Fir tree, now 20", S.40°W., 1.3 ft. uprooted and down, shows good scar. Did not chop open.
Remnants of Cedar stump S.58°E., 35.6 ft. Too far gone to find any markings.
Stump hole N.48°E., 32.3 ft.
New BTs -10" W.Fir N.55°W., 10.3 ft. mkd. T22S R6W S22 CS BT
10" W.Fir N.26°E., 25.4 ft. mkd. T22S R6W S23 CS BT.
8" W.Fir S.41°W., 21.1 ft. mkd. T22S R6W S27 CS BT.
No trees available in section 26.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #517, surveyed Aug/Sept. 1963 (DCSO records Vol. 32 Page(s) 13445)

The Sec. cor., monumented with a 1" T Iron, firmly set, recorded by Godfrey in 1961, from which the remains of the original bearing trees:

A sawed Fir stump 52" dia., bears S.58°E., 54 lks. dist., mkd. with a healed blaze. (Rec. calls for a Redwood)
A down Fir 24" dia., bears S.40°W., 2 lks. dist., mkd. with a healed blaze.
A down Fir 20" dia., bears N.22°W., 15 lks. dist. mkd. 22W on opened blaze and remarked T22S R6W S22 on bark blaze.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22, 23, 26 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

and the County Surveyors bearing trees
A Fir 10" dia., bears N.29°E., 38 lks. dist. mkd. T22S R6W
S23 CS BT on double blaze.

A Fir 10" dia., bears S.39½°W., 33 lks. dist. mkd. T22S
R6W S27 CS BT on double blaze.

A Fir 12" dia., bears N.55½°W., 15 lks. dist. mkd. T22S
R6W S22 CS BT on double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground,
with brass cap mkd:

T 22 S R 6 W
S 22 | S 23
S 27 | S 26
1963

from which a new bearing tree

A Fir 8" dia., bears S.77°E., 174 lks. mkd T22S R6W S26 BT
Reset the T iron alongside the iron post.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral
Surveyor, under Group No. 2500, Surveyed July/Aug. 2010 -
(DCSO records Vol. 57 Page(s) 22809 & Survey plat 2012-1)

The cor. of secs. 22, 23, 26, & 27, monumented with an iron
post, 2½" dia., firmly set, flush with ground, (alongside of
which is a "T" shaped iron bar, 3/4" dia., firmly set,
projecting 3" above ground, with a brass washer on top, mkd.
MILFORD N. HAINES SURVEY 239 DRAIN ORE., with a tack in
center), with a brass cap (properly) mkd.

from which the remains of the original bearing trees

A sawed, decayed fir stump, 52" dia., bears S.58°E., 35.6
ft., with no marks visible.

A roothole bears S.40°W., .3 ft., alongside of which is an
uprooted, decayed fir stump, size indeterminate, with
no marks visible.

A roothole bears N.22°W., 9.9 ft., alongside of which is
an uprooted, decayed fir stump, 20" dia., with axe
marks visible on a decayed, opened blaze.

and bearing trees mkd. Godfrey, in 1961

A fir, 30" dia., bears N.29°E., 25.1 ft., with a healed
double blaze,

A fir, 17" dia., bears S.39½°W., 21.8 ft., with a healed
double blaze.

A fir, 30" dia., bears N.55½°W., 9.9 ft., with a healed
double blaze,

and a new accessory

A rebar, 30" long, 5/8" dia., driven 28" in the ground for
a reference monument, bears S.47°13'55"E., 18.34 ft.
with an aluminum cap mkd. RM T22S R6W S26 18.3 FT TO
COR 2010 and an arrow pointing to the cor. CONT

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22, 23, 26 and 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Corner is located S.89 $\frac{3}{4}$ °E., 66.3 ft. from a wood post at the cor. of barbed-wire fences extending N.88°W. and South. Corner is further located 205 ft. W. of a gravel road, 11 ft. wide, bears N. and S.