

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1441)

Set post cor. of secs. 14, 15, 22 and 23, from which
A Fir 15" dia., bears N.58°W., 53 lks. dist.
A Fir 8" dia., bears N.36°E., 31 lks. dist.
A Fir 60" dia., bears S.71°E., 103 lks. dist.
A Fir 10" dia., bears S.15°W., 55 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy & C. Putnam, crew - Sept. 1, 1961 - C.S. File 49/143-70

Corner Report Only
Found - Haines "T" iron and cap. (unrecorded, no source record found, April 1995, J.Crawford; V.Laugen)
36" Fir tree with Haines metal disc nailed to it bears N.44°E., 20.4 ft. I chop in to tree facing cor. 110 yrs. (ring count). No scribing or face found.
60" Fir bears S.77°E., 69.0 ft. (to center of tree) This tree has been chopped open at least 150 years. No face or scribing found.
No other trees found. No scribed trees found.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #517, surveyed Aug/Sept. 1963 (DCSO records Vol. 32 Page(s) 13446)

The Sec. cor., monumented with a 1" T Iron firmly set, protruding 10" above the ground, mkd. by Haines, from which the remaining original bearing trees:

A Fir 36" dia., bears N.43 3/4°E., 31 lks. dist., no marks remaining on opened and rotted face. (Rec. bearing N.36°E.)
A Fir 67" dia., bears S.77°E., 103 lks. dist., no marks remaining, this tree was opened before I located the cor. (Rec. brg. S.71°E.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 22 S R 6 W
S 15 | S 14
S 22 | S 23
1963

from which new bearing trees

A Cedar 11" dia., bears N.59 1/4°E., 61 lks. dist. md. T22S R6W S14 BT.
A Fir 13" dia., bears S.58 1/2°E., 81 lks. dist. mkd. T22S R6W S23 BT.
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

A Fir 6" dia., bears S.32½°W., 51 lks. dist. mkd. T22S R6W S22 BT.
A Fir 15" dia., bears N.79¼°W., 81 lks. dist. mkd. T22S R6W S15 BT.
Reset the T iron alongside iron post.

BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1702, Surveyed July/Aug. 1993 - (DCSO records Vol. 51 Page(s) 19436)

The original sec. cor., monumented with an iron post, 2½" dia., firmly set, projecting 3" above the ground, with a 1963 brass cap attached, from which the remains of the original bearing trees:

A sawed Fir stump 68" dia., bears S.77°E., 103 lks. dist., with axe marks on a rotted blaze.

A sawed Fir stump 36" dia., bears N.43 3/4°E., 31 lks. dist., no marks remaining.

and the remains of bearing trees mkd. by Beck:

A Cedar snag 18" dia., bears N.59¼°E., 61 lks. dist., with a healed blaze.

A Fir 20" dia., bears S.58½°E., 81 lks. dist., with a healed blaze.

A sawed Fir stump 12" dia., bears S.32½°W., 51 lks. dist., with a healed blaze.

A Fir 21" dia., bears N.79¼°W., 81 lks. dist., with a healed blaze.

and new bearing trees:

A Cedar 20" dia., bears N.15°E., 46 lks. dist., mkd. T22S R6W S14 BT.

A Fir 8" dia., bears S.18°W., 52½ lks. dist., mkd. T22S R6W S22 BT.

The corner is located on a SE. slope at the intersection of wire fences, extending N. and E.

Harvey Christensen - for Rosboro - Mar. 1996 - M 123-49

CORNER REPORT ONLY

Found - 18" R.Cedar, N.21°E., 29.8 ft. - open face
18" R.Cedar, N.64°E., 40.1 ft. - healed face (snag)
21" D.Fir, S.54°E., 53.7 ft. - healed face
9" D.Fir, S.24°W., 34.3 ft. - open face
21" D.Fir, N.76°W., 53.4 ft. - healed face

continued next page

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Stephen Stys - Wit: Patrick Coy & Jack Jarrett - 8/7/2024 -
C.S. File 65/113-48

-
- Found - A 3¼" brass cap on a 2½" iron pipe (properly) mkd.,
1" T-iron along south side of monument.
 - A 24" R.Cedar, with visible scribe in face and tag
bears N.21°E., 29.8' (Per M123-49).
 - A 18" R.Cedar snag, with tag bears N.64°E., 40.1'
(Per M123-49).
 - A 29" D.Fir, with healed face bears S.54°E., 53.7'
(Per M123-49).
 - A 17" D.Fir, with healed face and tag bears S.24°W.,
34.3' (Per M123-49).
 - A 20" D.Fir stump, bears N.76°W., 53.4' (Per
M123-49).
 - New BT - An 8" D.Fir, faced & scribed "NW S23 BT" with X-chop
and tag bears S.80°E 15.3'.
 - Note - Compass decl. 14½°E.