

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1444)

Set ¼ sec. post, from which
A W.Oak 15" dia., bears S.53°W., 40 lks. dist.
A W.Oak 12" dia., bears N.45°E., 139 lks. dist.

George Scroggin - Survey of Plat of Sunnydale Orchards - Aug. 6, 1914 - Plat Vol. 5 Page 20 A&B

Iron pipe

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - Sept. 1961 - C.S. File 49/143-79

Found - 1/2" pipe at corner as called for in plat "Sunnydale Orchards".
Oak about 20", S.53°W., 26.4 ft., tree uprooted and down, badly rotted, found scribing.
Did not find NE BT.
Set alongside 1/2" pipe, brass cap mkd: County Surveyors Office 1961 T22S R6W ¼ S3|S2.
New BTs -18" W.Oak N.31°E., 80.0 ft. mkd. ¼ S2 CS BT, all in one blaze.
(?) W.Fir S.16°W., 106.7 ft. mkd. ¼ S3 CS BT.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 11/1/2001 - C.S. File 66/29-22

Found - 1961 DCSO brass cap iron pipe, protrudes 10" above ground. 1914
3/4" I.D. iron pipe along East edge of BC/IP, protrudes 2" out of ground.
18" now 21" dia., dead W.Oak, burnt & rotted, no scribing found, bears N.31°E., 80.0 ft. (tree standing)
Area around corner logged approx. 10-15 years ago, heavy brush.
1961 W.Fir BT not standing, stump not looked for.
New - 5" D.Fir, double blazed & scribed "X S2 BT" bears N.15°E., 10.1 ft.
5" D.Fir, double blazed & scribed "X S3 BT" bears N.40°W., 25.3 ft.
5" D.Fir double blazed & scribed "X S2 BT" bears S.40°E., 23.0 ft.
Compass Decl. 17½°E.

Fd. OK by H. Christensen, Oct. 2004 -M145-69