

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1440)

Set ¼ sec. post, from which
A Fir 30" dia., bears N.75°W., 66 lks. dist.
A B.Oak 5" dia., bears S.28°W., 42 lks. dist.

Wilford N. Haines - Dec. 1958 - M 14-23

Found - Stub of 30" Fir BT, N.75°W., 66 lks.
Madrone N.55°W., 80.2 ft. scribed ¼ S CS, must have been scribed by Britt, 1887.
Set Lot marked 1" x 1" x 36" T Iron with brass cap perpetuated "Survey Point-Wilford N. Haines #239".
Scribed -12" Fir S.39°W., 24.4 ft.
BT on Madrone (??)

Fd. OK, Aug. 1990 - M 110-47

BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1702, Surveyed July/Aug. 1993 - (DCSO records Vol. 51 Page(s) 19437)

The original ¼ sec. cor., perpetuated and recorded by Haines in 1958, monumented with a T shaped iron rod, 1' dia., firmly set, projecting 4' above the ground, with a brass disk attached to the top, mkd. WILFORD N HAINES 239 SURVEY POINT DRAIN ORE, from which the remains of an original BT:

A rotted Fir stump 24" dia., bears N.75°W., 66 lks. dist., no marks remaining.
and a tree reported by Haines:
A Madrone 50" dia., bears N.55°W., 124 lks. dist., with a rotted out blaze.
and the remains of a bearing tree mkd. by Haines:
A roothole bears S.39°W., 37 lks. dist., with a down and rotted Fir alongside, 10" dia., no marks remaining.

At the corner point

Set an stainless steel post, 28" long, 2 1/2" dia., 24" in the ground, directly over the iron rod, with brass cap mkd:

T22S R6W
1/4 $\frac{S\ 23}{S\ 26}$
1993

from which a new bearing tree:

A Fir 5" dia., bears S.15°W., 38½ lks. mkd. ¼ S26 BT.
Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

cont.

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2500, Surveyed July/Aug. 2010 - (DCSO records Vol. 57 Page(s) 22809 & Survey plat 2012-1)

The ¼ sec. cor. of secs. 23 and 26, monumented with an iron post, 2½" dia., firmly set, projecting 2" above ground, with a brass cap (properly) mkd.

from which the remains of an original bearing tree

A sawed, decayed fir stump, size indeterminate, bears N.75°W., 43.6 ft., with no marks visible.

and a BT mkd. by person(s) unknown, reported by Bedell

A madrone, 52" dia., bears N.55°W., 81.8 ft., with no marks visible on a partially healed, decayed blaze.

and the remains of a bearing tree mkd. by Haines, in 1958

A roothole bears S.39°W., 24.4 ft., uphill of which is on uprooted, decayed fir, size indeterminate, with no marks visible on an opened, decayed blaze.

and a bearing tree mkd. by Bedell

A fir, 8" dia., bears S.15°W., 25.4 ft., with a healed blaze.

David Edwards - For: Bear Creek Timber Co. & LGB Timber LLC
- 1/2016 - M170-33

Found - BLM brass cap

52" triple madrone N.55°W., 81.8'

8" dead fir S.15°W., 25.4'

New - 9" oak scribed "¼ S23 BT" bears N.7°E., 31.0'

No trees available in sec. 26.