

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 540320

PRIMARY CORNER DESCRIPTION South Center 1/16 cor. Sec. 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Wilford N. Haines - Dec.1958 - M 14-23

Set Lot marker, 1" x 1" x 36" T Iron with brass cap inscribed
"Survey Point-Wilford N. Haines #239".
Scribed -10" Fir N.39°E., 10.1 ft.
10" Fir N.37°W., 13.8 ft.

Douglas Co. Surveyors Office - M. Lenora Ladig, L.E. Monrean,
crew - Feb. 23, 1976 - C.S. File 59/8-5

Found - An orig. 10" now 14" Fir, alive and well with
visible scribe "1/16 S BT" and Haines cap nailed
on face, bears N.37°W., 13.8 ft.
No trace of Haines T-iron or NE BT, both destroyed
by old skid road.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 6 W
C
S1/16 | S23
C
1976

from which
An 8" Fir bears S.19°W., 48.0 ft. scribed "SC 1/16
S23 CS BT" in double blaze.

BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under
Group #1702, Surveyed July/Aug. 1993 - (DCSO records Vol. 51
Page(s) 19437-38)

The center S 1/16 cor., established and recorded by Haines in
1958, and reset from one remaining Haines bearing tree, after
the monument and NE. bearing tree were destroyed by road
construction by the DCSO in 1976, and is accepted as the
corner; monumented with an iron post, 1½" dia., firmly set,
projecting 8" above the ground, with 1976 brass cap attached,
from which a bearing tree mkd. by Haines:

A Fir 24" dia., bears N.37°W., 21 lks. dist., with a
healed blaze.
and a new bearing tree:
A Fir 8" dia., bears N.80°E., 20 lks. dist., mkd. CS 1/16
S23 BT.

The corner is located at the intersection of wire fences,
extending N. and SW.