

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 175400

PRIMARY CORNER DESCRIPTION West W.C. Sec. 17, 18, 19 and 20
sufficient

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

At 5 chs. West of true corner of Secs. 17, 18, 19, & 20 on
line bet. secs. 18 and 19

GLO survey by Gordon and Gardner, under Contract #52 dated
Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1505)

Set post, from which

- A Fir 30" dia., bears S.1°W., 112 lks. dist.
- A Fir 20" dia., bears N.28°W., 92 lks. dist.

Wilford Haines - For: R.D. Hungerford - March 1967 - M 32-72

(Set S.89°46'E., 72.80 chs. on line bet. secs. 18 and 19
Found - 20" Fir now a windfall, N.28°W., 92 lks.
Set ½" steel rod on old cat road on top of ridge and scribed
New BT - 12" Fir, West 14.3 ft.

Cor. checked by VRT, April 1967, not sufficient evidence to
renew - C.S. File 54/41-3

BLM resurvey by Jack W. Bowder, Cadastral Surveyor, under
Group #928, surveyed July/Aug. 1977 (DCSO records Vol. 40
Page(s) 16019)

The witness cor., perpetuated and recorded by Haines in 1967,
monumented with a steel rod ½" dia., firmly set, projecting
1" above ground, from which the remains of an original
bearing tree:

- A root hole bears N.28°W., 92 lks. dist. with a down Fir
alongside 36" dia., no marks visible.
- and a bearing tree mkd. by Haines:
A Fir 15" dia., bears West, 21½ lks. dist. with healed
blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground,
directly over steel rod, with brass cap mkd:

W C
T 22 S R 7 W
S 18 | S 17 >
S 19 | S 20 >
1977

from which a new bearing tree

A Fir 10" dia., bears S.59°E., 40 lks. dist. mkd. X BT.
(True point for the cor. of secs. 17, 18, 19 and 20, falls on
precipitous E. slope, where it is impracticable to establish
a permanent monument.)

Fd. Ok by K. DeGroot, 12/2006 - M146-51