

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page 1506)

-----  
Set ¼ sec. post, from which  
A Fir 12" dia., bears S.33°W., 191 lks. dist.  
A W.Oak 10" dia., bears S.62°E., 80 lks. dist.

Floyd Cole, Deputy - Wit: J. Traylor; G. Baylor ; - June 18, 1913 - Vol. 2 Pg. 189; Field Book 32 Pg. 26 (and "old" cor. book, Page 23)

-----  
Renew corner from original trees, Fir still standing. Oak stump in evidence.

Wilford N. Haines - For: Yoncalla Lumber Co. - March 1961 - M 22-1

-----  
Found - Stump of orig. Fir BT. (1855)  
Stumps of 2 Fir BTs scribed about 1915.  
Set 1" x 1" x 36" T. Iron and scribed:  
6" Fir N.87°E., 48.4 ft.  
8" forked Fir N.65°W., 110.5 ft.

BLM resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #928, surveyed July/Aug. 1977 (DCSO records Vol. 40 Page(s) 16019-20)

-----  
The ¼ sec. cor., perpetuated and recorded by Haines in 1961, when original evidence was still in existence, monumented with an iron rod, 1" dia., firmly set, projecting 6" above ground, from which a bearing tree mkd. by Haines:

A Fir 12" dia., bears S.88 ¾°E., 73 lks. dist. with healed blaze.  
and the remains of a bearing tree of which I have no record  
A sawed Fir stump 25" dia., bears S.33 ¾°E., 15½ lks. dist. with scribe marks 4 S visible on open blaze.

At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:  
T 22 S R 7 W  
¼  
S 18 S 17  
1977

from which a new bearing tree  
A Fir 8" dia., bears N.71 ¾°W., 77½ lks. dist. mkd. ¼ S18 BT.