

PRIMARY CORNER DESCRIPTION Sec Cor for 8, 9, 16 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO rec. Vol. 4 Page 1524)

Set post cor. to secs. 8, 9, 16 and 17, from which
A Maple 10" dia., bears N.54°E., 38 lks. dist.
A Fir 24" dia., bears S.55°E., 11 lks. dist.
A Fir 30" dia., bears S.52°W., 55 lks. dist.
A Fir 36" dia., bears N.68°W., 24 lks. dist.

Wilford N. Haines, #239 - For: Yoncalla Lumber Co. - March 1961 - M 22-1

Found 2 original BTs, SE BT down, NW BT a stump.
Set 1" x 1" x 36" T Iron.
Scribe - 5" Fir S.70°W., 21.0 ft.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - March 1962 - C.S. File 52/14-114

Found - Fir 36" S.55°E., 7.3 ft. uprooted and down, good bark scribing visible on under side "S16 T2 R7W".
48" Fir stump N.68°W., 15.8 ft. Bark mostly gone from side facing corner. No scars or scribing fd.
Badly rotted remnants of old Maple stump N.54°E., 25 ft.

No trace found of SW BT.
5" Fir scribed by Haines in 1961 bears S.61°W., 17.7 ft. scribed "S17 T22S R7W BT".

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 7 W
S 8 | S 9
S 17 | S 16
1962

New BTs- 4" D.Fir N.60°W., 9.1 ft. mkd. S8 CS BT.
4" D.Fir S.25°E., 25.8 ft. mkd. S16 CS BT.
No suitable tree near in NE quadrant.
Haines T Iron set in 1961 bears S.70°E., 4.7 ft.
Fence corner, fences W. and N. bears N.82°W., 8 ft.

Fd. OK, May 5, 1989, L. Roberts - C.S. File 63/91 & M 108-22

Troy Rambo - For: Seneca Jones Timber - Mar. 2004 - M144-19

Found - The record BTs in place.
Rec. 4"DF, S.25°E., 25.8 ft. now a snag.
New - Scribed "S16 BT" on 10" FD, bears S.25°E., 15.4 ft.

continued next page

PRIMARY CORNER DESCRIPTION Sec Cor for 8, 9, 16 and 17

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Harvey Christensen - For: Seneca Jones Timber Co. - Aug. 2006
- M151-45

Found - 3.25" 1962 BLM brass cap, 0.4' above ground.
54" D.Fir N.3°E., 19.8 ft., bark rescribing visible
11" D.Fir S.1°W., 40.9 ft., partial scribing face
visible, rescribed tree "T16S R7W S9 BT". As
section line runs to south side of tree, hand
compass bearing correct 19° East.
60" D.Fir, N.70°W., 31.7 ft. (Slope), 2 foot stump,
no scribing visible.
New - 18" D.Fir, S.63°W., 40.9 ft. blazed & scribed "T22S
R7W S8 BT"
10" D.Fir, N.74°W., 21.2 ft. blazed & scribed "T22S
R7W S4 BT"
6' steel post 0.5' north.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral
Surveyor, under Group No. 2892, surveyed April/May 2018-
(DCSO records Vol. 59 Page 23745-6)

The cor. of secs. 8, 9, 16, and 17, perpetuated by Godfrey in
1962; further perpetuated by Rambo in 2004; further
perpetuated by Christensen in 2006; monumented with an iron
post, 1¼" dia., firmly set, projecting 10" above ground, with
a brass cap (properly) mkd.

from which the remains of the original bearing trees

A roothole bears S.55°E., 7.3 ft., downhill of which is a
down decayed fir, 36" dia., no marks visible and a
broken top.

A sawed decayed fir stump, 48" dia., bears N.68°W., 15.8
ft., no marks visible.

and a bearing tree mkd. by Haines

A fir, 25" dia., bears S.60¼°W., 17.7 ft., with a healed
blaze.

and the remains of the bearing trees mkd. by Godfrey

A sawed fir stump, 20" dia., bears S.24¼°E., 25.8 ft.,
with a healed blaze.

A broken, decayed fir stump, 14" dia., bears N.62¼°W., 9.1
ft., with a healed blaze.

and a bearing tree mkd. by Rambo

A fir, 13" dia., bears S.27¼°E., 15.4 ft., with a healed
blaze.

and new bearing trees

A fir, 9" dia. bears N.81½°E., 17.7 ft. mkd T22S R7W S9 BT

A fir, 3" dia., bears N.56¼°W., 20.8 ft., mkd. X BT.

Continued next page

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 8, 9, 16 and 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From this cor., a point erroneously positioned from original evidence for the cor. of secs. 8, 9, 16, & 17, by Haines, in 1961; rejected by Godfrey, Douglas County Deputy Surveyor, in 1962; and was not used for control in this survey; bears S.68°01'45"E., 4.80 ft.; monumented with a "T" shaped iron rod, 3/4" dia., firmly set, projecting 6" above ground, with brass washer mkd. WILFORD N. HAINES 239 SURVEY POINT DRAIN, ORE., with a tack in center, from which the bearing tree mkd. by Haines

A fir, 25" dia., bears S.70½°W., 21.0 ft., with a healed blaze (This tree was used again for the true point.) Corner is located E., 65 ft., of graveled road, 12 ft. wide, bears N.20°W. and S.25°E.

NAD 1983 (2011)

Latitude: 43°39'50.24" N. Longitude: 123°32'44.99" W.