

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 & 21 (Wit. Cor)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1512)

(West bet. secs. 16 & 21, at 35.50 chains)
Set post on bluff bank of Elk Creek, from which
A Fir 30" dia., bears S.35°W., 4 lks. dist.
A Laurel 4" dia., bears N.52°E., 12 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - March 1962 - C.S. File 52/14-120

Found - Badly burned Fir snag, S.35°W., 2.6 ft. chop open scar and find excellent scribing "S21 T22S R7W BT".

No trace found of Laurel BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 7 W
W C S 16
S 21
1962

New BTs -9" D.Fir S.55°W., 22.9 ft. mkd. W.C. S21 CS BT.

6" D.Fir N.17°E., 39.2 ft. mkd. W.C. S16 CS BT.

Corner lies on very steep NW slope, approx. 150 ft. West of top of hill. Top of vertical rock cliff, 10 ft. high, lies 4.0 ft. NW of corner.

Cor. Fd. and tied in BLM resurvey by Jelley and Beck, Cadastral Surveyors, under Group #590, surveyed July/Sept. 1965 (DCSO records, Vol. 33 Page 13961)

(Added marks BLM 1965 to brass cap)