

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Dep. Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Pages 1522-23)

-----  
Set post cor. to secs. 3, 4, 9 and 10, from which  
No tree convenient in sec. 3.  
A Cedar 24' dia., bears S.60°E., 14 lks. dist.  
A Maple 14" dia., bears S.50°W., 52 lks. dist.  
A Maple 14" dia., bears N.55°W., 10 lks. dist.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664, dated May 23, 1896 (DCSO records Vol. 4 Page(s) 1545)

-----  
Found post badly decayed; some of the bearing trees are down; at same point, I reestablish this cor. as follows:  
Set a sandstone 12 x 10 x 6 ins., 8" in the ground for cor. of sec. 3, 4, 9 and 10, mkd. with 5 notches on S. and 3 notches on E. edges, from which  
A Fir 30" dia. bears S.38½°E. 148 lks. mkd. T22S R7W S10 BT  
A Maple 14" dia. bears S.50°W. 51 lks. mkd. T22S R7W S9 BT  
A Maple 14" dia. bears N.55°W. 10 lks. mkd. T22S R7W S4 BT  
No other trees within limits, raised a mound of stone, 2 ft. base, 1½ ft. high W. of cor.

Wilford Haines - For: Woolley Logging Co. - 9/1960 - M 11-72

-----  
Found 2 original BTs and rock.  
Set 1" x 1" x 36" T Iron by rock.  
Scribe - 20" Fir N.85°E., 7.0 ft.

Ronald L. Rice, Ward NW - For: Seneca Jones Timber Co. - 12/2003 - M 143-57

-----  
Found - Org. Stone & 1" Haines "T" iron along side  
44" D.Fir stump bears S.38½°E., 97.7', healed face  
29" Maple bears N.55°W., 6.6', healed face  
25" D.Fir snag bears N.85°E., 7.0', healed face  
New - 17" D.Fir bears S.74°E., 70.9', blazed, scribed  
"T22S R7W S10 BT"  
21" W.Fir bears N81°W 25.0', blazed, scribed "T22S R7W S4 BT"

Note: All corners have 5½" galvanized steel post adjacent to the cor. monument. Corner accessories have red painted band & face plus yellow BT tag where appropriate.

Found Ok by D. Edwards, Nov. 2004 - M145-72