

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. cor. for 23 & 24 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Page(s) 1532)

Set post cor. to secs. 23, 24, 25 and 26, from which
A Fir 4" dia., bears N.50°E., 30 lks. dist.
A Willow 4" dia., bears S.60°E., 24 lks. dist.
A Fir 5" dia., bears S.50°W., 10 lks. dist.
A Maple 5" dia., bears N.25°W., 15 lks. dist.

GL0 survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 4 Page(s) 1542)

I find the cor. of secs. 23, 24, 25 and 26 in a delapidated condition, and reestablish same to refer to the secs. on the North only, from the bearing tree in sec. 23, as follows:
Set a sandstone 14x8x6 ins., 9" in the ground for cor. of sec. 23 and 24, mkd. with 1 notch on E. edge; from which
A Maple 5" dia., bears N.25°W., 15 lks. dist. mkd. T22S R7W S23 BT.
A Fir 6" dia., bears N.31½°E., 44 lks. dist. mkd. T22S R7W S24 BT.

Wilford N. Haines, #239 - For: E.G. Whipple - Oct. 1957 - C.S. File 42/309 and M 1-59

Set from original BTs.
1" x 1" x 36" Iron rod with brass cap inscribed Wilford N. Haines #239 Survey Point.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy & C Putnam, crew - May/June 1962 - C.S. File 52/14-104

Found - Haines T Iron and cap at corner.
27" D.Fir N.31½°E., 29.0 ft. cut open and found good scribing on old face "S" and part of an "R". I reblaze and rescribe this tree "T22S R7W S24 CS BT"
Rotted stump and Maple stool N.25°W., 9.9 ft. No scars or scribing found, too badly decayed.
No scars or scribing found of other orig. BTs.
New BT - 29" D.Fir S.23°E., 13.3 ft. mkd. T22S R7W S23 & 24 CS BT.
No good trees near to NW.
Did Not Set Brass Cap.

(Cont. Next Page)

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. cor. for 23 & 24 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Gary L. Langlitz, A. Vic Cangie, M. Lenora Ladig, crew - Dec. 29, 1975 - C.S. File 57/39-48

Found - 1" x 1" T Iron set by Haines.
Only remaining orig. BT, a 6" now 23" D.Fir with orig. scribe marks and rescribing by Godfrey visible on unhealed blaze, bears N.31½°E., 29.0 ft.
A BT mkd. by Godfrey, a 29" now 32" D.Fir alive and well healed, bears S.23°E., 13.3 ft.
Set 1" x 30" I.P. with brass cap attached mkd:
Douglas Co. Surveyors
T 22 S R 7 W
S 23 S 24
S 26
1975

We place Haines T Iron alongside the brass cap.

BLM resurvey by Wayne L. Rogers and Lance J. Bishop, Cadastral Surveyors, under Group #1160, surveyed April/July 1984 - (DCSO records Vol. 47 Page(s) 18078)

The sec. cor., perpetuated and recorded by Godfrey in 1962, further perpetuated and recorded by Langlitz in 1975, monumented with an iron post 1¼" dia., firmly set, projecting 3" above ground with 1975 brass cap, from which the remaining original bearing tree:

A Fir 28" dia., bears N.31½°E., 44 lks. dist., no marks visible on opened blaze.
and a bearing tree mkd. by Godfrey
A Fir 30" dia., bears S.23°E., 20 lks. dist., with healed blaze.
and a new bearing tree
A Maple 8" dia., bears S.86 3/4°W., 80 lks. dist. mkd. T22S R7W S26 BT.
No suitable tree available in NW. quadrant.

Survey by Ken Hoffine - For: Lone Rock Timber Co. - March 1990 C.S. File 63/104-34

Found - Corner is a 1" I.P. with DCSO brass cap.
1" x 1" T Iron set by Haines alongside cap.
26" D.Fir bears N.31½°E., 29.0 ft. healed face with both county and BLM BT tags. Orig. BT.
34" D.Fir bears S.23°E., 13.3 ft. well healed face with both County and BLM BT tags.

(Cont. Next Page)

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. cor. for 23 & 24 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found BT of no record: (see above BLM survey notes)
8" Maple bears West, 52.5 ft., scribing visible, no BT tag so put up a Lone Rock Timber location tag with above information.

Fd. OK, Jun. 1995, K. Hoffine, C.S. File 65/1-5

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2824, surveyed May 2016/March 2018 - (DCSO records Vol. 59 Page(s) 23877)

The cor. of secs. 23 and 24 only, monumented with an iron post, 1¼" dia., firmly set, projecting 10" above ground (alongside of which is a "T" shaped iron rod ¾" dia., firmly set, projecting 10 ins. above ground, with brass washer mkd. WILFORD N. HAINES 239 SURVEY POINT DRAIN, ORE with a tack in center), with brass cap (Properly) mkd. from which the remains of a BT mkd. by Nicklin in 1897
A decayed fir stump, 27" dia., bears N.31½°E., 29.0 ft., with no marks visible on partially opened blaze.
and the remains of a bearing tree mkd. by Godfrey in 1962
A decayed fir stump, 30" dia., bears S.23°E., 13.2 ft., with a healed double blaze.
and the remains of a BT mkd. by Rogers and Bishop in 1984
A root hole bears N.86¾°W., 52.8 ft., downhill of which is a maple log, size indeterminate, with a healed blaze. (Record, S.86¾°W.)
and new bearing trees
A fir, 7" dia., bears N.9°E., 13.0 ft. mkd T22S R7W S24 BT
A fir, 9" dia., bears N.87½°W., 17.5 ft., mkd. T22S R7W S23 BT.
Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center & each monument established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. Angle iron driven alongside each monument.