

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Page(s) 1517)

Set ¼ sec. post, from which
A Cedar 30" dia., bears N.1°E., 26 lks. dist.
A Maple 6" dia., bears West, 15 lks. dist.

J.W. Cole - Dec.1915 - Vol. 2 Page 245; Field Book 64 Pages 17-25 (and "old" cor. book page 22)

Renew cor. by setting a 4" x 4" x 3½' Cedar post, mkd. CS S13, S14 ¼ S on S., E., W. and N. sides, from which
The remains of Cedar witness tree bears N.1°E., 26 lks. and which John Hancock testifies is original witness tree.

Mark:
A Fir 72" dia., bears N.5°15'E., 142 lks. dist.
A Fir 72" dia., bears S.58°30'E., 154 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy & C Putnam, crew - Dec/Jan. 1961 - C.S. File 52/14-119

Found - Haines T Iron and cap at corner.
Also find Cedar stake set by Cole, rotted off.
Old Fir stump N.5¼°E., 93.7 ft., badly burned, no scribing found.
Stump hole with remains of Fir stump in place, S.58½°E., 101.6 ft.
Remnants of old Cedar stump N.1°E., 17.2 ft., no scribing. (Orig.)
22" Fir N.11°E., 41.3 ft., open scar, pitch covered, shows scribing, probably mkd. by Haines.
Set alongside T Iron, brass cap mkd: County Surveyors Office
T22S R7W ¼ S14|S13
1961
New BT - 15" R.Cedar S.78½°W., 29.8 ft. mkd. ¼ S14 CS BT.

Fd. OK, April 1993, K. Hoffine, M 117-4

Ken Hoffine - For: Lone Rock Timberland Co. - Nov. 2009 - M160-18

Found - Douglas County cap with Haines T-iron 0.25 ft. north of corner.
27" Cedar bears N.78°E., 29.8 ft. as per rec. healed face & BLM tag.
continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Rotten 44" D.Fir stump bears N.10°E., 41.5 ft. as per rec. no marks.
41" D.Fir bears N.43°W., 125.0 ft. as per rec. healed face & tag.
Rotten 60" D.Fir stump bears N.5°E., 93.7 ft. no marks.
13" down D.Fir bears N.49°E., 12.0 ft. as per rec.
Corner lies on flat ground approx. 2.5 chains west of Brush Creek. Recent clear cut north of corner.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2824, surveyed May 2016/March 2018 - (DCSO records Vol. 59 Page(s) 23882-3)

The 1/4 sec. cor. of secs. 13 and 14, perpetuated by Cole, in 1915; further perpetuated by Haines, date unknown, as reported and further perpetuated by Godfrey, in 1961; and perpetuated by Hoffine, in 1993 from original evidence no longer in existence, monumented with an iron post, 1 1/4 dia., firmly set, projecting 7" above ground, with brass cap (properly) mkd.
from which the remains of the bearing tree mkd. by Haines, reported by Godfrey
A decayed fir stump, 30" dia., bears N.10 1/4° E., 41.6 ft., with axe marks visible.
and a bearing tree mkd. by Haines, reported by Hoffine
A fir, 44" dia., bears N.42 3/4°W., 125.6 ft., with a healed blaze.
and a bearing tree mkd. by Godfrey
A cedar, 29" dia., bears S.78 3/4°W., 29.7 ft., with a healed blaze.
and a bearing tree by Hoffine
A root hole bears N.44 1/4°E., 12.3 ft., alongside of which is a down fir log, 14" dia with a healed blaze
and a new bearing tree
A fir, 12" dia., bears S.19 1/4°E., 48.0 ft., mkd. 1/4 S13 BT. Each new BT has a 2 1/2"x 1/4" magnetic nail (Mag Nail) driven at the base right side-center & each monument established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. Angle iron driven alongside each monument.