

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,
dated Sept. 1856

Set post NW cor. Claim 47, from which
A Fir 40" dia., bears N.67°E., 84 lks.
A Fir 40" dia., bears S.70°E., 152 lks.

F. C. Frear, Deputy Co. Surveyor - Wit: Chas. Clements; F.B.
Soloman - Sept. 1917 - Field Book 43 Page 13

Renew from old BTs.
Set in 1½" x 30" Iron pipe, from which
A 60" Fir bears N.67°E., 84 lks. dist., old tree.
An 18" Fir bears S.62°E., 47 lks. dist., old tree.
A 10" Fir bears S.02½°E., 31 lks. dist., old tree.

BLM resurvey by Floyd A. Brooks and James E. Jelley,
Cadastral Surveyors, under Group #'s 514 and 350, surveyed
June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13733-34)

The NW. cor. of Claim No. 46, perpetuated and recorded by
Frear in 1917, monumented with an iron pipe, 1½" dia., 8"
above ground, firmly set, from which the original bearing
trees:

- A sawed Fir stump 65" dia., bears N.67°E., 84 lks. dist.,
with a healed blaze.
- A down Fir 40" dia., bears S.70°E., 152 lks. dist., with
no marks remaining.

and bearing trees mkd. by Frear:

- A down Fir 15" dia., bears S.57°E., 44 lks. dist., with a
healed blaze.
- A sawed Fir stump 24" dia., bears S.4°E., 34 lks. dist.,
with no marks remaining.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground,
with brass cap mkd:

T 22 S R 8 W
S 17 | C 46
1963

from which new bearing trees

- A Fir 22" dia., bears S.15°E., 68 lks. dist. mkd. T22S R8W
C46 BT.
- A Fir 9" dia., bears N.41°W., 59 lks. dist. mkd. T22S R8W
S17 BT.

Reset the iron pipe alongside the iron post.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION NW Cor. Simon Allensworth DLC #46

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Bruce Shaner, surveyed for - Ronald & Annie Meints; June-July 1996 - M 125-25 & corner reports in CS 65/8-1D

- Found - 1963 U.S.B.L.M. Brass Cap w/iron pipe.
 - 28" W.Fir BT, face overgrown, bears S.15°E., 44.9 ft
 - 22" W.Fir BT, face overgrown, bears N.41°W., 38.9 ft
 - 1½" iron pipe sets alongside B.C.
 - D.Fir(stump) BT, 65" dia badly rotted, bears N.67°E. 55.4 ft.
- New - Set 6 foot steel fence post at brass cap. No trees available in SW or NE quadrant.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2180 & 2300, surveyed May/Oct. 2007 (DCSO records Vol. 56 Page(s) 22230-1)

The NW cor. of DLC 46, in sec. 17, perpetuated by Frear in 1917, and remonumented by Brooks and Jelley in 1963-65; monumented with an iron post, 2½" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd. from which the remains of the original bearing trees

- A decayed fir stump, 48" dia., bears N.67°E., 55.4 ft., with a healed blaze.
- A roothole bears S.70°E., 100.3 ft., alongside of which is a down decayed fir, size indeterminate, no marks visible.

from which the remains of a bearing tree mkd. by Frear and reported by Brooks and Jelley

- A decayed fir stump, size indeterminate, bears S.57°E., 29.0 ft., no marks visible. (Record, down fir.)

and the bearing trees mkd. by Brooks and Jelley

- A W.Fir, 34" dia., bears S.15°E., 44.9 ft., with a healed blaze.
- A W.Fir, 26" dia., bears N.41°W., 38.9 ft., with a healed blaze. Tree falls behind two firs, each 4" dia.

The Frear iron pipe, 1½" dia., firmly set, projecting 6" above ground, as reset by Brooks and Jelley, and a steel fence post are alongside the cor.

Corner is located on a broad spur, slopes S.45°E., in hole cut in decayed fir log, 36" dia., at the NW. cor. of timber, edge bears S and E, with older fir reproduction to N and W, and N., 600 ft. from a creek, 2 ft. wide, course S.80°E.