

PRIMARY CORNER DESCRIPTION SW Cor. Simon Allensworth DLC 46

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy, dated Sept. 1856

Set post SW cor. Claim 46, from which
An Oak 24" dia., bears S.25°E., 40 lks.
An Alder 15" dia., bears N.83½°E., 560 lks.

F. C. Frear, Deputy Co. Surveyor - Witnesses, Chas. Clements; F.B. Soloman - July 1917 - Field Book 43 Page 13

Renew from old Govt. BTs.
Set in 1½" x 24" galv. iron pipe, from which
A 20" Fir bears N.9°W., 05 lks. dist.
A 30" Fir bears S.79¼°W., 10 lks. dist.

BLM resurvey by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13733)

The SW. cor. of Claim No. 46, on the N. bdy. of Claim No. 51, determined at record bearing and distance from bearing trees mkd. by Frear in 1917, when the original bearing trees were existent:

A sawed Fir stump 30" dia., bears S.79¼°W., 10 lks. dist., with fragmentary scribe marks visible on opened blaze.
A down Fir 28" dia., bears N.9°W., 5 lks. dist., with a healed blaze.

At the corner point
Set an iron post, 28" long, 2½" dia., 21" in the ground, with brass cap mkd:
T 22 S R 8 W
S 17|C 46

C 51
1963

from which new bearing trees:
An Oak 12" dia., bears N.7°E., 114 lks. dist. mkd. T22S R8W C46 BT.
A Fir 25" dia., bears S.57°E., 41 lks. dist. mkd. T22S R8W C51 BT.
A Fir 10" dia., bears N.50°W., 78 lks. dist. mkd. T22S R8W S17 BT.

Found OK, by B. Shaner, June 1996 M 125-25 & C.S. 65/8-1B

continued next page

PRIMARY CORNER DESCRIPTION SW Cor. Simon Allensworth DLC 46

Alias	Description

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2180 & 2300, surveyed May/Oct. 2007 (DCSO records Vol. 56 Page(s) 22229-30)

The SW cor. of DLC 46, on the N. bdy. of DLC 51, in sec. 17, perpetuated by Frear in 1917, and remonumented by Brooks and Jelley in 1963-65; monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd.

from which the remains of the bearing trees mkd. by Frear and reported by Brooks and Jelley

A decayed fir stump, size indeterminate, bears S.79¼°W., 6.6 ft., no marks visible.

A roothole bears N.9°W., 3.3 ft., alongside of which is a down fir, 28" dia., no marks visible.

and the bearing trees mkd. by Brooks and Jelley

An oak, 16" dia., bears N.7°E., 75.2 ft., with a healed blaze.

A W.Fir, 37" dia., bears S.57°E., 27.1 ft., with a healed blaze.

A fir, 26" dia., bears N.50°W., 51.5 ft., no marks visible.

Corner is located on a spur ridge, slopes E.

WC bears N.0°08'31"E., 199.74' (See C.S. 65/008-1 for B. Shaner's report) from the corner:

A point established on the W. bdy. of Donation Land Claim No. 46, in sec. 17, by Shaner, in 1996, and is accepted as a witness point for the W. bdy. of DLC 46; monumented with an iron rod, 5/8" dia., firmly set, projecting 4" above ground, with aluminum cap mkd. SHANER ENGR RLS 430, from which the bearing trees mkd. by Shaner

A maple, the smallest and southwesterly of a clump of three, 19" dia., bears N.31°E., 23.6 ft., with scribe marks PC BT visible on bark.

A fir, 61" dia., bears S.7¾°W., 27.5 ft., with scribe marks PC BT visible on bark.

A steel fence post is alongside the cor.

Corner is located on a NE. slope, and S., 105 ft. from a creek, 3 ft. wide, course S.55°E.