

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 054030

PRIMARY CORNER DESCRIPTION SW Cor. Daniel Test DLC #54

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,
dated Sept. 1856

Marked a Hemlock 15" dia. for SW cor., from which
A Cedar 36" dia., bears N.55°W., 37 lks.
A Cedar 12" dia., bears N.9°E., 135 lks.

BLM resurvey by Floyd A. Brooks and James E. Jelley,
Cadastral Surveyors, under Group #'s 514 and 350, surveyed
June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13715-16)

The SW. cor. of Claim No. 54, monumented with the remains of
the original cor. tree; a decayed Hemlock stump, 24" dia.,
with no marks remaining, from which the original bearing
trees:

A Cedar 40" dia., bears N.9°E., 142 lks. dist. with no
marks visible on opened blaze. (Rec. dist. 135 lks.)
A down Cedar 48" dia., bears N.55°W., 37 lks. dist. with
fragmentary scribe marks visible on burned face of
blaze.

At the corner point through decayed stump,
Set an iron post, 36" long, 1" dia., 34" in the ground in
center of stump, with brass cap marked: T 22 S R 8 W
S 33 | C 54
1964

from which new bearing trees:

A Cedar 17" dia., bears N.48°E., 113 lks. dist. mkd. T22S
R8W C54 BT.
A Fir 17" dia., bears S.74½°E., 79 lks. dist. mkd. T22S
R8W S33 BT.

Douglas Co. Surveyors Office - John M. Powell and crew - July
12, 1973 - C.S. File 56/34-4

Found - Both 1964 Cadastral BTs, alive and in good
condition, Fir healed, Cedar has scribe visible
on partially healed blaze.

1964 Cadastral brass cap was found in creek bottom.
RESET at the corner point and also reset steel fence post
alongside.

This corner lies on East bank of small creek, course North,
and in very dense underbrush.

Ken Hoffine for Lone Rock Timber Co. Oct. 1994 - C.S. File
63/154-23

(Cont. Next Page)

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 054030

PRIMARY CORNER DESCRIPTION SW Cor. Daniel Test DLC #54

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found - BLM 2½" brass cap on 1" iron pipe buried in mud of the washed out bank on the stream, rotten hemlock stump remains (orig. corner) washed out down stream.

We reset monument by distances given in the 1964 corner notes of the bearing trees for the corner.

BTs Fd- 46" Western R.Cedar bears N.10°E., 93.7 ft. (rec. N.9°E., 93.72 ft.)

25" D.Fir bears S.74°30'E., 52.1 ft. BLM tag, healed scar.

28" Western R.Cedar bears N.49°30'E., 74.3 ft. (rec. N.48°E., 74.58 ft.) BLM tag, healed scar.

New Accessories -

We tagged 46" Western Red Cedar. We painted faces and painted "BT" on trees.

Corner lies in the bottom of a small creek bed. The creek lies in a steep North-South ravine.