

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 202 survey dated March 11, 1874 (DCSO records Vol. 4 Page(s) 1632)

Set a post for ¼ sec. cor. A Dogwood 4 ft. long, 5" dia., 18" in ground, from which
A Fir 10" dia., bears N.10°E., 22 lks. dist.
A Fir 10" dia., bears S.65°W., 18 lks. dist.

GLO survey by Geo. F. Rigby, U.S. Cadastral Engineer, under Group #143, surveyed Oct/Nov. 1931 - (DCSO records Vol. 27 Page(s) 11646-47)

The point of the orig. ¼ sec. cor. of secs.19 and 24 is determined from the orig. bearing trees from which the overgrowth has been chopped and the marks burned. At this point:

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for ¼ sec. cor., with brass cap mkd:

¼
S 24|S 19
1931

from which old bearing trees:

A Fir 18" dia., bears N.10°E., 22 lks. dist. marks all burned off.

A Fir 28" dia., bears S.65°W., 18 lks. dist. marks all burned off.

New bearing trees:

A Fir 10" dia., bears N.88°45'E., 106 lks. dist. mkd. ¼ S19 BT.

A Fir 18" dia., bears N.55°W., 55 lks. dist. mkd. ¼ S24 BT.

I had no 1" iron post for this cor. but having 2" posts to spare, I monumented the corner with one of them.

Fd. OK in BLM survey by Brooks and Peterson, under Group #'s 595 and 657 - surveyed Aug. 1965/Dec. 1967)DCSO records, Vol. 34 Page 14108

Found OK by Quimby, February 1997 - M 124-42

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2149, surveyed Aug. 2006/Oct. 2006 - (DCSO records Vol. 55 Page(s) 21739)

The ¼ sec. cor. of secs. 19 and 24, on the E. bdy. of the Tp., monumented with an iron post, 2" dia., firmly set, projecting 10" above ground, with brass cap (properly) mkd.
continued next page

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 19; & 24, T22-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of an original bearing tree
A burned decayed fir snag, 19" dia., bears S.65°W., 13.3 ft., no marks visible. (Record, 11.9 ft.)
and the remains of the bearing trees mkd. by Rigby in 1931
A decayed fir stump, 30" dia., bears N.88³/₄°E., 70.0 ft., no marks visible.
A fir, 46" dia., bears N.55°W., 36.3 ft., with a healed blaze.
and a new bearing tree
A fir, 5" dia., bears N.59¹/₄°E., 49.6 ft., mkd. ¹/₄ S19 BT.
Tree is located E. of graveled road, 12 ft. wide, bears N.20°W. and S.30°E., and W. of abandoned graveled road, 10 ft. wide, bears N.10°W. and S.10°E., 75 ft. to junction.
Corner is located on W. edge older fir reproduction, edge bears N. and S., with an aluminum fence post alongside the cor.