

PRIMARY CORNER DESCRIPTION Sec. cor. for 8, 9, 16 and 17

|                     |                                      |
|---------------------|--------------------------------------|
| Alias <u>047040</u> | Description <u>W NW cor. DLC #47</u> |
| Alias _____         | Description _____                    |
| Alias _____         | Description _____                    |
| Alias _____         | Description _____                    |

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1574)

-----  
Set post cor. to secs. 8, 9, 16 and 17, from which  
A Dogwood 8" dia., bears N.55°W., 24 lks. dist.  
A Fir 8" dia., bears S.56°W., 22 lks. dist.  
A Fir 5" dia., bears S.10°E., 39 lks. dist.  
A Fir 50" dia., bears N.60°E., 5 lks. dist.

GLO survey by W.H. Byars, Deputy Surveyor under contract # 202 survey dated March 11, 1874 (DCSO records Vol. 4 Page(s) 1592)

-----  
Find the timber hereabouts fell in all directions. Rails made and hauled off but can find no trace of old lines or cor.  
I mark a Fir 10" dia., without witness trees for cor.

F.C. Frear, Deputy County Surveyor - Wit: Chas Clements; F.B. Soloman - Sept. 1917 - Field Book 43 Page 12; Vol. 3 Page 1 (and "old" corner book, page 26)

-----  
Renew corner from old BTs.  
Set in 1½" x 40" Iron pipe, from which  
A 30" Fir bears S.56°W., 22 lks. dist. Old tree.  
A 24" Fir bears S.10°E., 39 lks. dist. Old tree.  
A 72" Fir bears N.60°E., .05 lks. dist. Old tree.  
A 34" Fir bears N.31¼°W., 48 lks. dist. Old tree.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - M. Stone & V. Tracy, crew - Dec. 1962 - C.S. File 52/14-49

-----  
Found - 1½" x 40" I.P. set by Frear in 1917, pulled out of ground by uprooted tree.  
16" Dogwood N.55°W., 15.8 ft., cut open and find good scribing, top of tree broken off, but remaining part still alive.  
28" W.Fir snag S.56°W., 14.5 ft., cut open and find Frear's scribing.  
26" W.Fir stump S.10°E., 25.7 ft., stump hollow, on piece of wood inside stump, still attached. Find portion of old face with original scribing visible "16 22S R8W"  
72" D.Fir N.60°E., 3.3 ft. recently uprooted, part of Frear's scribing "S9" visible in bark.  
38" D.Fir N.31¼°W., 31.7 ft., recently uprooted, face buried in mud.

(Cont. Next Page)

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec. cor. for 8, 9, 16 and 17

Alias 047040 Description W NW cor. DLC #47  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Set Brass cap at cor. mkd: County Surveyors Office  
T 22 S R 8 W  
S 8 | S 9  
S 17 | S 16  
1962

Reset I.P. alongside.  
New BTs -9" Hemlock N.30°W., 72.3 ft. mkd. T22S R8W S8 CS BT  
6" W.Fir N.47½°E., 53.6 ft. mkd. T22S R8W S9 CS BT  
12" W.Fir S.57°E., 69.4 ft. mkd. T22S R8W S16 CS BT  
9" W.Fir S.84°W., 80.8 ft. mkd. T22S R8W S17 CSBT.

BLM resurvey by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13696-97)

-----  
The sec. cor., remonumented and recorded by Fred Darby, County Surveyor in 1962, monumented with an iron post, 1½" dia., 10" above ground, firmly set, with brass cap marked:

COUNTY SURVEYORS OFFICE  
T 22 S R 8 W  
S 8 | S 9  
S 17 | S 16  
1962

from which the original bearing trees:  
A down Fir 72" dia., bears N.60°E., 5 lks. dist., with fragmentary scribe marks visible in bark.  
A sawed Fir stump 26" dia., bears S.10°E., 39 lks. dist. with scribe marks 16 S22 R8W visible on rotted blaze.  
A Fir snag 28" dia., bears S.56°W., 22 lks. dist. with partial scribe marks visible on opened blaze.  
A Dogwood 16" dia., bears N.55°W., 24 lks. dist., with partial scribe marks visible on opened blaze.  
and bearing trees mkd. by Darby:  
A W.Fir 6" dia., bears N.47½°E., 81 lks. dist. with scribe marks T22S R8W S9 CS BT visible on unhealed blaze.  
A W.Fir 12" dia., bears S.57°E., 105 lks. dist. with scribe marks T22S R8W S16 CS BT visible on unhealed blaze.  
A W.Fir 9" dia., bears S.84°W., 122 lks. dist. with scribe marks T22S R8W S17 CS BT visible on unhealed blaze.  
A Hemlock 9" dia., bears N.30°W., 110 lks. dist. with scribe marks T22S R8W S8 CS BT visible on unhealed blaze.  
Add the marks B L M 1963 to brass cap.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 8, 9, 16 and 17

|                     |                                      |
|---------------------|--------------------------------------|
| Alias <u>047040</u> | Description <u>W NW cor. DLC #47</u> |
| Alias _____         | Description _____                    |
| Alias _____         | Description _____                    |
| Alias _____         | Description _____                    |

Les Roberts, surveyed for Meints, Jan. 1997 - M 126-32

-----  
Found - 1962 Douglas Co. iron pipe and brass cap.  
No 1962 bearing trees found.  
New - 14" Fir, N.89°W., 48.7 ft. (scribed/metal washer/  
painted red)  
14" Fir, S.06°E., 3.8 ft. (scribed/metal washer/  
painted red)

Found OK by C. Sweeden, Jan. 2001 - M136-34

Dependent resurvey by Edith M Forkner, Cadastral Surveyor,  
under Group #2180 & 2300, surveyed May/Oct. 2007 (DCSO  
records Vol. 56 Page(s) 22217-8)

-----  
The cor. of secs. 8, 9, 16, & 17, identical with the W-NW  
cor. of DLC No. 47, perpetuated by Frear in 1917, and by  
Godfrey in 1962-63, and accepted by Brooks and Jelley in  
1963-65; monumented with an iron post, 1½" dia., firmly set,  
projecting 5" above ground, with brass cap (properly) mkd.  
from which the remains of an original bearing tree

A roothole bears N.60°E., 3.3 ft., alongside of which is  
a down fir stump, 47" dia., with no scribe marks  
visible on open blaze.

and the remains of the BTs mkd. by Godfrey & reported by  
Brooks & Jelley as being mkd. by Fred Darby, Douglas County  
Surveyor, in 1962

A W.Fir, 28" dia., bears N.47½°E., 53.5 ft. with a healed  
blaze.

A decayed W.Fir snag, size indeterminate, bears S.57°E.,  
69.3 ft., no marks visible.

and the bearing trees mkd. by Roberts in 1997

A fir, 20" dia., bears S.9¾°E., 3.7 ft., with a healed  
blaze.

A fir, 21" dia., bears S.88¾°W., 47.7 ft., with a healed  
blaze.

and a new bearing tree

A fir, 13" dia. bears N.43°W. 67.4 ft. mkd. T22S R8W S8 BT  
An axle, 1½" dia., firmly set, projecting 15" above  
ground, and a steel fence post are alongside the cor.

Corner is located alongside roots of original fir stump, on  
a flat at the W end of a knob on an E slope, and SE, 20 ft.,  
from a abandoned dirt road, 8 ft. wide, extending S.20°W. and  
N.30°E., 50 ft. to tank trap, on the other side of which is  
a lightly maintained dirt road, 8 ft. wide, extending N.50°E.  
and S.85°W.