

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 140500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1675)

Set Fir post 4½ ft. long, 4½" sq., 24" in the ground, for ¼ sec. corner, marked ¼ S. on North face, from which,
A Fir 7" dia., bears N.17°15'E., 20 lks. dist. mkd. ¼ S BT
A Fir 7" dia., bears S.85°E., 32 lks. dist. mkd. ¼ S BT.

Two Fir BTs fd. and tied in survey by W. Haines, Feb. 1964 - M 27-33

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy, and crew - March 20, 1964 - C.S. File 52/14-82

Found - 12" Fir stump, N.17¼°E., 13.2 ft., previously opened, good scribing visible on old face "¼S"
Other BT not found.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 9 W
¼ $\frac{S 7}{S 18}$
1964

New BTs -5" Hemlock N.23½°W., 26.1 ft. mkd. ¼ S7 CS BT.
26" D.Fir N.32°E., 73.0 ft. mkd. ¼ S7 CS BT.
No trees near in section 18.

Cor. Fd. and used in BLM resurvey by Jelley, under Group #709, surveyed May/Sept. 1970 - (DCSO Records, Vol. 36 Page 14905)