

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1700)

-----

Set Maple post 4½ ft. long, 4" sq., 24" in ground on flat for ¼ sec. corner, marked ¼ S on the West face, from which  
A Fir 18" dia., bears S.80°E., 55 lks. dist. mkd. ¼ S BT.  
A Fir 24" dia., bears S.73°W., 28 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Dec. 1967 - C.S. File 54/60-17

-----

Found - Unrecorded 1¼" I.Pipe and brazed cap mkd. "¼ S30/¼ S29" at corner.

Orig. 18" now 42" Fir, decayed stump, S.80°E., 36.3 ft., open and find scribe.

Orig. 24" now 50" Fir, decayed stump, S.73°W., 18.5 ft., previously opened and shows "4S BT" scribe.

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S R 9 W

¼ S30 | S29

1967

Deposit old corner pipe alongside.

New BTs -9" D.Fir N.28°W., 62.1 ft. mkd. ¼ S30 CS BT.

7" D.Fir N.86°E., 61.4 ft. mkd. ¼ S29 CS BT.

This corner lies on S. edge of bench at foot of very steep ascent approx. 450 ft. N. of old logging road.