

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 207200

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 29 (SE Cor. Sec. 30)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1700)

-----

Set Alder post 4" sq., 4½ ft. long, 24" in ground for closing corner to secs. 29 and 30 mkd. C.C. on the N. and T22S on the E.; R9W S30 on the W. faces, with 1 groove on the S. and 5 grooves on the E. sides, from which,

A Fir 10" dia., bears N.29°E., 44 lks. dist. mkd. T22S R9W S29 BT.

A Fir 60" dia., bears S.8°W., 21 lks. dist. mkd. C.C. T22S R9W S29-30 BT.

A Fir 48" dia., bears N.45°W., 25 lks. dist. mkd. T22S R9W S30 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Dec. 1967 - C.S. File 54/60-21

-----

Found - Orig. 10" now 22" Fir decayed snag, 12 ft. high, N.29°E., 29.0 ft., previously opened, scribe visible. We open lower and find "BT" scribe.

Orig. 60" Fir, only partial burned out shell, S.18°W., 13.9 ft. No scribe, record bearing S.8°W.

Orig. 48" Fir now 50" stump, cut low, N.45°W., 16.5 ft. no scribe found.

Set Brass cap at cor. mkd: County Surveyors Office  
T 22 S R 9 W  
C.C. S30 | S29  
1967

New BTs -14" D.Fir N.83°E., 20.0 ft. mkd. T22S R9W S29 CC CS BT.

8" D.Fir N.66°W., 13.1 ft. mkd. T22S R9W S30 CC CS BT.

12" D.Fir S.47°E., 4.0 ft. mkd. T22S R9W CC CS BT.

This corner lies on steep, westerly slope approx. 160 ft. East of creek, course S.