

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 21

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1694)

Set Fir post 4½ ft. long, 4" sq., 24" in the ground, on hillside sloping NE. for ¼ sec. corner, mkd. ¼ S on the W. face, from which,
A Fir 16" dia., bears S.54°E., 114 lks. dist. mkd. ¼ S BT.
A Fir 36" dia., bears S.27°W., 28 lks. dist. mkd. ¼ S BT.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16058)

The ¼ sec. cor. of secs. 20 and 21, determined from the remains of the original bearing trees:
A Fir 50" dia., bears S.52°E., 114 lks. dist., with scribe marks BT visible on open blaze. (Rec. S.54°E.)
A decayed Fir snag, 38" dia., bears S.31°W., 28 lks. dist. with old axe marks visible on decayed blaze. (Rec. S.27°E.)
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 22 S R 9 W
¼
S 20 S 21
1975
from which a new bearing tree:
A Fir 21" dia., bears N.55½°W., 54 lks. dist. mkd. ¼ S20 BT.

Cor. Fd. and Used in BLM resurvey by Malloy and Farnsworth, under Group #'s 1125 and 1226, surveyed Nov/Dec. 1982 - (DCSO records, Vol. 47 Page 17938)