

PRIMARY CORNER DESCRIPTION Sec. cor. for 16, 17, 20 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1638)

Set a Maple post 40" long, 5" dia., 12" in ground, for corner to secs. 16, 17, 20, and 21, from which,
A Maple 6" dia., bears N.45°E., 38 lks. dist.
A Maple 8" dia., bears S.78°E., 84 lks. dist.
A Fir 24" dia., bears S.40°W., 34 lks. dist.
A Fir 60" dia., bears N.45°W., 45 lks. dist.

GL0 survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1693-94) and duplicated on page 1713)

The Sec. cor., which I reestablished as follows:
Set an Alder post, 4½ ft. long, 4" sq., 24" in the ground on hillside sloping North, marked T22S S16 on the NE.; R9W S21 on the SE.; S20 on the SW.; and S17 on the NW. faces, with 2 notches in the S. and 4 notches on the E. edges, from which,
A Fir 24" dia., bears S.45°W., 34 lks. dist. mkd. T22S R9W S20 BT.
A Fir 60" dia., bears N.40°W., 55 lks. dist. mkd. T22S R9W S17 BT.
I marked:
A Maple 6" dia., bears N.41°E., 37 lks. dist. mkd. T22S R9W S16 BT.
An Alder 6" dia., bears S.17°E., 33 lks. dist. mkd. T22S R9W S21 BT.

Survey by H. T. Lewis, Engineer #22 - Sept. 29, 1939 - C.S. File 16/55 (and "old" corner book, page 28) Recorded by H.L. Eppstein.

At the sec. corner, I found the SW witness tree in place, also faint marks on the rotten bark of the 60" Fir described in the govt. notes, but no evidence of corner post. I therefore: Set a Fir post 4 ft. long, 4" dia., 14" in ground, from which:
A Maple 14" dia., bears N.31°E., 33 ft. mkd. T22S R9W Sec. 16, BT 722.
A Fir 30" dia., bears N.14°W., 30 ft. dist. mkd. T22S R9W Sec. 17 BT 722.
A Hemlock 8" dia., bears S.50°E., 7 ft. dist. mkd. T22S R9W Sec. 21 BT 722.

(Cont. Next Page)

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec. cor. for 16, 17, 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy -
Vernon "Ray" Tracy, crew - June 1962 - C.S. File 49/103-6

Found - 4" squared stake at corner.
Fir, now 40", N.14°W., 30.0 ft., 2 scars very plain.
Tree in good condition. Lewis BT.
Hemlock now 18", S.50°E., 7.0 ft. Scars plain. Tree
in good condition. Lewis BT.
Maple now 22", N.E. 33.0 ft. very plain scars. Tree
in good condition.
Rotted remains of Fir snag, N.40°W., 36.3 ft. No
scars or scribing found. O.B.T.
Fir stump now 64", S.45°W., 22.4 ft. Good bark
scribing visible, T22S R9W S20. O.B.T.
No trace of other original BTs.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 9 W
S 17 | S 16
S 20 | S 21
1962

New BT - 10" Hemlock S.32°W., 42.8 ft. mkd. T22S R9W S20 CS
BT.

Cor. Fd. and used in BLM resurvey by Wofford, etal, under
Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCS0
records Vol. 40 Page(s) 16058-59)

Fd. OK, March 1978 by Ronald Stuntzner, M 69-36

Cor. Fd. and used in BLM resurvey by Malloy and Farnsworth,
under Group #'s 1125 and 1226, surveyed Nov/Dec. 1982 - (DCS0
records Vol. 47 Pages 17938-39)